

It is the intent of the tank(s) owner, to report a summary of activities related to the abatement of spilled or released Petroleum or Hazardous Substances. This document is submitted as a confirmation of those United States Environmental Protection Agency notification requirements in 40 CFR, Part 280.62, [b].

NOTIFICATION OF RELEASE RESPONSE ACTIVITIES


OWNERSHIP OF TANK(S)	LOCATION OF TANK(S)
Name: <u>SOUTHEAST AIRPORT</u>	Site Name: <u>SOUTHEAST AIRPORT</u>
Address: <u>6328 MONNETT ROAD</u> <u>CLIMAX, NC 27233</u>	Address: <u>6328 MONNETT ROAD</u> <u>CLIMAX, NC 27233</u>
Phone Number: <u>(919) 674-7663</u>	County: <u>GUILFORD COUNTY</u>

INITIAL NOTIFICATION		
As required in 40 CFR, Part 280.61 [a], upon confirmation of a release from a UST system the owner or operator is responsible for the notification of the release to the implementing state agency within 24 hours of such release.		
Notification By: <u>MICHAEL G. STONEMAN</u>	Notification Time: <u>1750</u>	Notification Date: <u>2-12-93</u>
Agency Notified: <u>GUILFORD COUNTY DEPT OF EMERGENCY SERVICES</u>	Contact: <u>SHARON CIHAK</u>	Phone: <u>333-6538 FAX 373-7565</u>

INITIAL ABATEMENT CHECK LIST	
As required in 40 CFR, Part 280.62 [a], upon confirmation of a release from a UST system the owner or operator is responsible for performing the following abatement measures relative to such releases. This check list is prepared to meet the requirements.	
<u>yes</u>	1.) Did the owner or operator remove as much of the regulated substance from the UST system, as was necessary to prevent further release to the environment?
<u>yes</u>	2.) Did the owner or operator visually inspect any aboveground releases or exposed belowground releases and prevent further migration of released substance into the surrounding soils and ground water?
<u>yes</u>	3.) Did the owner or operator continue to monitor and mitigate, any additional fire and safety hazards posed by vapors or free product that have migrated from the UST excavation zone and entered subsurface structures?
<u>yes</u>	4.) Did the owner or operator remedy hazards posed by contaminated soils that are excavated or exposed as a result of release confirmation, site investigation, abatement, or corrective action activities?
<u>yes</u>	5.) Did the owner or operator measure for the presence of a release where contamination is most likely to be present at the UST site?
<u>yes</u>	6.) Did the owner or operator investigate to determine the possible presence of free product and begin free product removal as soon it was practicable?
Comments: <u>UPON REMOVAL OF THE UST SYSTEM, SOIL SAMPLES WERE COLLECTED. BOTH TANK PITS SHOWED CLEAN LABORATORY ANALYSIS. PUMP ISLAND HAD TPH CONCENTRATIONS OF 632 PPM. ADDITIONAL SOIL REMOVED ON 2-11-93, WILL FORWARD POST-REMEDIATION SOIL SAMPLES IN FORM OF CLOSURE REPORT WHEN COMPLETED.</u>	

UST SYSTEM ABATEMENT OPERATIONS TO BE PERFORMED BY:	
(Contractor) Name: <u>FOUR SEASONS INDUSTRIAL SERVICES, INC.</u>	
Address: <u>PO BOX 16590 GREENSBORO</u>	State: <u>NC</u> Zip: <u>27416-0590</u>
Contact: <u>MICHAEL G. STONEMAN</u>	Phone: <u>(919) 273-2718</u>
<u>yes</u>	Is this contractor / operator knowledgeable of the requirements for the abatement and remediation of UST system releases?
<u>yes</u>	Is this contractor / operator and employees specifically medically monitored as required by DOL OSHA 29 CFR, Part 1910.120 [j] ?
<u>yes</u>	Is this contractor / operator and employees specifically Haz-Sub trained as required by DOL OSHA 29 CFR, Part 1910.120 [e] ?

Tank owners are required to notify the implementing state agency at least 20 days after the release notification as required in 40 CFR, Part 280.62 [b]. For further information contact the U. S. Environmental Protection Agency RCRA / Superfund Hotline at 800-424-9346

Submitted By: MICHAEL G. STONEMAN Signature:  Date: 2-12-93