




PIEDMONT ENVIRONMENTAL SERVICES, INC.

P.O. Box 18631
Greensboro, NC 27419
(919) 668-4821



November 18, 1991

Kelly Gage
Guilford County Emergency Services
PO Box 18807
Greensboro, NC 27419

Re: Piedmont Triad International Airport
Tanks I-A, III-A, III-B, and III-C

Dear Mrs. Gage;

On November 12 we removed one 6000 #2 heating oil tank from the above site. On the notice of closure intent form this tank was labeled tank I-A. There were no signs of contamination in this hole and the tank was in good condition. Because this tank is a non regulated tank, no soil samples were taken.

On November 7 we removed (3) underground storage tanks also from this site. These tanks were located at the intersection of Old Oak Ridge Road and Inman Road. The tanks were one 1000 gallon gas tank, one 2000 gas tank, and one 275 gallon kerosene tank.

Attached is the site map showing the orientation of the tanks and the sampling locations. The old store at this site has been demolished. There were no pumps or a pump island left; however, it appeared that the pumps were over the point where the two gas tanks met. There was no evidence of contamination at this site.

The samples were collected from a depth of 8½ feet below surface grade. The samples were taken from the bucket of our backhoe in tubes provided by the laboratory. The samples were stored in an ice cooler until delivery to the lab. The chain of custody form and the sample results are attached.

All attachments are associated with the (3) regulated tanks removed from the Old Oak Ridge Road site. The heating oil tank was located at the CFR station for the airport.

If anything further is needed please let me know.

Sincerely,


Thad Chesson

cc: Chris Colenda

Environmental Center
Series

1/2 1/4 0
Scale One Half Mile — Revised 1988
Piedmont Aerial Surveys, Greensboro, N.C.

UNIDENTIFIED STREETS IN VICINITY MAY NOT BE SHOWN.



Oak Ridge Road
site


PIEDMONT TRIAD INTERNATIONAL AIRPORT

QUAKER ACRES

FRIENDSWOOD

Jaman Road →

⊗ = sample locations
all samples taken at 8½ feet





GUILFORD LABORATORIES, INC.

P.O. Box 9735/Plaza Station/Greensboro, N.C. 27408

11-14-1991

REPORT OF ANALYSIS

Customer : PIEDMONT ENVIROMENTAL
PO BOX 18631
GREENSBORO N.C. 27419
ATTN: SHERWOOD CHESSON

Job # : PES11107
P.O. # : AIRPORT OAK RID

Samples : # 4940 2000 GAL GAS NORTH
4941 2000 GAL GAS SOUTH
4942 1000 GAL GAS NORTH
4943 1000 GAL GAS SOUTH
4944 275 GAL KEROSENE

RESULTS

	4940	4941	4942	4943	4944
TPH as Gasoline by EPA 5030(ppm)	<10	<10	<10	<10	<10
TPH by EPA 3550 (ppm)					<10

Guilford Laboratories, Inc.

J. A. Rayburn
J. A. Rayburn

GUILFORD LABORATORIES
Chain Of Custody Form

Matrix Codes:

- S = Soil
- WM = Waste Water
- DM = Dr-ink Water
- GM = Ground Water
- 0 = Other

Sampler's Name : RES

Sampling Date : 11/7/91

Sampling Time : 12:00 (p/a)

Sampling Site : Airport Lake Ridge

Sample Description

2000 gms north Matrix S Container tube Preservation cool Analysis 5030

1000 gms South Matrix " Container " Preservation " Analysis "

1000 gms North Matrix " Container " Preservation " Analysis "

1000 gms South Matrix " Container " Preservation " Analysis "

225 Kerosene Matrix " Container " Preservation " Analysis 5030 13550

Relinquished by : [Signature] Date: 11/7/91 Time 2:04 (p/a)

Received by : [Signature] Date: 11/7/91 Time 3:04 (p/a)

Relinquished by : _____ Date: ____/____/____ Time ____:____ (p/a)

Received by : _____ Date: ____/____/____ Time ____:____ (p/a)

Relinquished by : _____ Date: ____/____/____ Time ____:____ (p/a)

Received by : _____ Date: ____/____/____ Time ____:____ (p/a)

Relinquished by : _____ Date: ____/____/____ Time ____:____ (p/a)

Received by : _____ Date: ____/____/____ Time ____:____ (p/a)

Guilford Labs Phone : 919-854-2320

RECEIVING REPORT

From: Piedmont

Received by: Carboth
SAFEWAY TANK DISPOSAL, INC.

Transported by: Piedmont

Tank Disposal Number	Size	Weight	Product	Date Received	Origin
5005	6000		Diesel Fuel	11-12-91	Airport Greensboro NC.

Safeway Tank Disposal, Inc. accepts the liability for the tank(s) and contents on this report. The tank(s) and contents must be a petroleum product. If at any time the tanks are found to contain any product other than a petroleum product SAFEWAY TANK DISPOSAL, INC. has the right to refuse disposal or negotiate a price for disposal. Customer will be liable for any clean-up or other cost resulting from contamination by a substance other than a petroleum product.

Safeway Tank Disposal, Inc. agrees to dispose of petroleum tanks and contents in accordance with local, state, and federal regulation. Certificate of Disposal to follow.

Carboth
SAFEWAY TANK DISPOSAL, INC.

Site Investigation Report For Permanent Closure of U.S.T.

TANKS IN NC Return Completed Form To:
 The appropriate DEM Regional Office according to the county of the facility's location.
 [SEE MAP ON REVERSE SIDE OF OWNER'S COPY (BLUE) FOR REGIONAL OFFICE ADDRESS].

Sate Use Only
 I.D. Number _____
 Date Received _____

INSTRUCTIONS

Please complete and return within (30) days following completion of site investigation.

I. Ownership of Tank(s)	II. Location of Tank(s)
Piedmont Triad Airport Authority	same
Owner Name (Corporation, Individual, Public Agency, or Other Entry) PO Box 35005	Facility Name or Company
Street Address Guilford	Facility ID # (if available)
County Greensboro NC 27425	Street Address or State Road
City (919) 665-5600	County City Zip Code
Area Code Telephone Number	Area Code Telephone Number

III. Contact Person

Name: **Edward A. Johnson** Job Title: **Dir. of Development** Telephone Number: **(919) 665-5600**

Closure Contractor: **Piedmont Environmental Services PO Box 18631 Greensboro, NC 27419**
 (Name) (Address)
 Lab: **Guilford Laboratories PO Box 9735 Greensboro, NC 27408**
 (Name) (Address)

IV. U.S.T. Information				V. Excavation Condition				VI. Additional Information Required	
Tank No.	Size in Gallons	Tank Dimensions	Last Contents	Water in Excavation		Free Product		Notable Odor or Visible Soil Contamination	
				Yes	No	Yes	No	Yes	No
1	1000	46" x 12'	gas		X		X		X
2	2000	64" x 12'	gas		X		X		X
3	275	48" x 3'	kerosene		X		X		X

See reverse side of blue copy (owner's copy) for additional information required by N.C. - DEM in the written report and sketch.

VII. Check List

Check the activities completed.

- Contact local fire marshal
 - Notify DEM Regional Office before abandonment.
 - Drain & flush piping into tank.
 - Remove all product and residuals from tank
 - Excavate down to tank.
 - Clean and inspect tank.
 - Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submersible pumps and other tank fixtures.
 - Cap or plug all lines except the vent and fill lines.
 - Purge tank of all product & flammable vapors.
 - Cut one or more large holes in the tanks.
 - Backfill the area.
- Date Tank Permanently closed: 11/7/91

- ABANDONMENT IN PLACE**
- Fill tank until material overflows tank opening;
 - Plug or cap all openings;
 - Disconnect and cap or remove vent line
 - Solid inert material used - please specify: _____
- REMOVAL**
- Create vent hole
 - Label tank
 - Dispose of tank in approved manner
- Final tank destination: Safeway Tank Disposal

VIII. Certification (Read and Sign)

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete.

Print name and official title of owner or owner's authorized representative	Signature	Date Signed
Thad Chesson VP Piedmont Environmental		11/18/91