

**UST CLOSURE
INSPECTION CHECKLIST**

Inspector's Name Sharon K. Chab Date August 29, 1995

I SITE INFORMATION

Facility/Site Name: OVERMAN PAINT Co.
 City/Town: 5018 HOOPER ROAD County: GUILFORD
 Owner: RANDY OVERMAN Phone: (910) 697-9203
 Operator: _____ Phone: _____
 Contractor: PETROLEUM EQUIPMENT + SERVICE INC. Phone: (910) 294-3199
 Laboratory: _____ Phone: _____
 Directions: _____

Date of scheduled UST Removal (from GW/UST-3): 8-29-95

II UST STATUS

Tank #:	1	2	3	4	5	6	7	8
Size:	<u>500</u>							
Product:	<u>GASOLINE</u>							

Remark Y (YES), N (NO), NA (NOT APPLICABLE), and U (UNKNOWN) for each of the following:

III CLOSURE PROCEDURES

U Tanks, tools, equipment bonded or grounded?
U OSHA/Safety violations observed: _____

Y Product in piping drained into tank?
Y Tanks properly purged? Method: Dry ice
Y Tanks emptied and cleaned properly?
Y Accessible openings capped or plugged except 1/8" vent?
N UST(s) closed in place and filled with solid inert material?
 Final destination of tank(s): Safeway Tank Disposal
 Final destination of product, contaminated soil, contaminated water, etc. _____

IV SITE DESCRIPTION

Y Soil stained and/or petroleum odor?
Y Contaminated soil excavated? Quantity? (estimate): 5 cubic yards
Y Soil samples taken of excavated soil left on site?
 Excavated soil on plastic or trucked away? (Circle one)
 Tank(s) condition: _____
 Product line condition?: _____

V SAMPLING LOCATION

Y USTs < 20': one at each end?
N USTs > 20': one at each end & middle?
NA Samples every 20' of piping?
NA Samples under each tank island?
N Water samples? (in lieu of soil samples)
 Samples: floor, side, stockpiled soil?: _____

VI SAMPLE COLLECTION QUALITY CONTROL

Collection method: (Shovel, auger, back hoe): *glove hand, glass jar*
 How Preserved? (ice):
 Tools decontaminated: (soap, Di-H₂O, MEOH, organic-free H₂O).
 Chain-of-Custody form (required):

VII SUMMARY OF SITE CONDITIONS

Groundwater intersected?
 Bedrock encountered?
 Contaminated soil?
 Free product in excavation?

VIII SAMPLES COLLECTED BY DEM PERSONNEL

Samples collected?
 Sample locations:

XV COMMENTS:

O₂ < 8% before pulling
tank was corroded and has numerous 1/8" holes in it.
Samples smelled very faintly of gas.

DIAGRAM OF SITE INVESTIGATION AT UST CLOSURE

Diagram should include physical structures such as roads, buildings, etc.; former location of USTs, pumps, product lines; soil sampling locations; and location of excavated soil.

