POLLUTION INCIDENT/U.S.T. LEAK REPORTING FORM

Department of Environment, Health, Natural Resources
Division of Environmental Management
GROUNDWATER SECTION

Update

Confirm. GW Contamination (Y/N) ____
Major Soil Contamination (Y/N) ____
Minor Soil Contaminatin (Y/N) ✓

Incident # 10177

Date Incident Occurred or Leak Detected 9/21/92

INCIDENT DESCRIPTION

Incident Location/Name Crosscreek Apparel - Distribution Center

Address Highway 52 S. & Holly Springs Rd 27030

City/Town Mt Airy | County Surry | Region WSRO

Briefly Describe Incident

After removal of 10K fuel oil tank, samples indicated there had been a release. Dugout.

POTENTIAL SOURCE OWNER-OPERATOR

Potential Source Owner-Operator Crosscreek Apparel, Inc/Bill Inman | Telephone 919-789-6161

Company | Street Address Hwy 52 S.

City Mt Airy | County Surry | State NC | Zip Code 27030

OWNERSHIP
0. N/A 1. Municipal 2. Military 3. Unknown (4. Private) 5. Federal 6. County 7. State

OPERATION TYPE
0. N/A 1. Public Service 2. Agricultrural 3. Residential 4. Educational/Relig. 5. Industrial (6. Commercial) 7. Mining

POLLUTANTS INVOLVED

MATERIALS INVOLVED	AMOUNT LOST	AMOUNT RECOVERED
10K — #2 Fuel	?	?

SOURCE OF POLLUTION

PRIMARY SOURCE OF POLLUTION (Select one)
1. Intentional dump
2. Pit, pond, lagoon
(3. Leak-underground)
4. Spray irrigation
5. Land application
6. Animal feedlot
7. Source unknown
8. Septic tank
9. Sewer line
10. Stockpile
11. Landfill
12. Spill-surface
13. Well
14. Dredge spoil
15. Nonpoint source

PRIMARY POLLUTANT TYPE (Select one)
1. Pesticide/herbicide
2. Radioactive waste
3. Gasoline/diesel
(4. Heating oil)
5. Other petroleum prod.
6. Sewage/septage
7. Fertilizers
8. Sludge
9. Solid waste leachate
10. Metals
11. Other inorganics
12. Other organics

LOCATION
(1. Facility)
2. Railroad
3. Waterway
4. Pipeline
5. Dumpsite
6. Highway
7. Residence
8. Other

SETTING
1. Residential
(2. Industrial)
3. Urban
4. Rural

Site Priority Ranking O/E

D.E.M. Regional Contact Cindy Rintoul | Signature Cindy Rintoul | Date 4-16-93

GW-61 Revised 3/92



From Mount Airy South, NC
USGS Quad 1970

ENGINEERING TECTONICS, P.A.
Winston-Salem, N.C (919) 724-6994

Cross Creek Apparel	92-322-E

Site Location Map

Feet
2000 0 2000

Drawn by:	Approved by:

Figure 1