

# UST-2

## Site Investigation Report for Permanent Closure or Change-in-Service of UST

**FOR TANKS  
IN  
NC**

**Return completed form to:**  
The DWM Regional office in the area the facility is located. SEE MAP ON THE BACK OF THIS FORM FOR REGIONAL OFFICE ADDRESSES. Return the yellow copy to the Central Office in Raleigh so that the status of the tank may be changed to "PERMANENTLY CLOSED".

STATE USE ONLY  
LID # \_\_\_\_\_  
Date Received \_\_\_\_\_

### I. OWNERSHIP OF TANKS

Unknown Oilhan Tanks  
Owner Name (Corporation, Individual, Public Agency, or Other Entity)  
Street Address \_\_\_\_\_  
City \_\_\_\_\_ County \_\_\_\_\_  
State \_\_\_\_\_ Zip Code \_\_\_\_\_  
Area Code \_\_\_\_\_ Phone Number \_\_\_\_\_

### II. LOCATION OF TANKS

R-Way II  
Facility Name or Company D-009763  
Facility ID # (if known) 6414 US Hwy 15B  
Street Address Summerfield, Guilford  
City \_\_\_\_\_ County \_\_\_\_\_ Zip Code \_\_\_\_\_  
Area Code \_\_\_\_\_ Phone Number \_\_\_\_\_

### III. CONTACT PERSONNEL

Name Bruce Zamackors Job Title NCDEMR Project Mgr Tel. No. 919-733-1325  
Closure Contractor Sol Solutions Address 1703 Vantage St. Winston-Salem Tel. No. 336-725-5844  
Primary Consultant Solutions-IES Address 3722 Benson Dr, Raleigh, NC Tel. No. 919-875-1060  
Lab PACE Analytical Address 9800 Kliney Ave. Suite 100, Huntville, NC No. 704-875-9092

### IV. UST INFORMATION

### V. EXCAVATION CONDITION

### VI. ADDITIONAL INFORMATION

Tank No.	Size in Gallons	Tank Dimensions	Last Contents	Water in excavation		Free product		Notable odor or visible soil contamination	
				Yes	No	Yes	No	Yes	No
1	4,000	5x24	gas/diesel		X	X		X	
2	4,000	5x24	gas/diesel		X	X		X	

See reverse side of pink copy (owner's copy) for additional information required by NC DWM in the written report and sketch.  
**NOTE:** If a release from the tank(s) has occurred, the site assessment portion of the tank closure must be conducted under the supervision of a P.E. or L.G., with all closure site assessment reports bearing the signature and seal of the P.E. or L.G.

### VII. CHECKLIST (CHECK THE ACTIVITIES COMPLETED)

#### PERMANENT CLOSURE (For Removal or Abandonment-in-Place)

- Contact local fire marshal
- Notify DWM Regional Office before abandonment
- Drain and flush piping into tank
- Remove all product and residuals from tank
- Excavate down to tank
- Clean and inspect tank
- Remove drop tube, fill pipe, gauge pipe, vapor recovery tank connections, submersible pumps, and all other tank fixtures
- Cap or plug all lines except the vent and fill lines
- Purge the tank of all product and flammable vapors
- Cut one or more large holes in the tank
- Backfill the area

Date tank(s) Permanently Closed: 6/21/05  
Date of Change in-service: \_\_\_\_\_

#### ABANDONMENT IN PLACE

- Fill tank until material overflows tank opening
- Plug or cap all openings
- Disconnect and cap or remove vent line
- Solid inert material used -specify \_\_\_\_\_

#### REMOVAL

- Create vent hole
- Label tank
- Dispose of tank in approved manner. Final tank destination: \_\_\_\_\_

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true accurate and complete

Print name and official title of owner or owner's authorized representative  
Krian Wright / Staff Geologist / Solutions-IES

Signature  
[Signature]

Date Signed  
7/1/05

UST-2 Rev 02/2001

White copy - Regional Office

Yellow Copy - Central Office

Pink Copy - Owner