

Hazardous Waste Compliance Data Entry Form – Side A

NC5000000661

EPA ID Number: None

Facility Name: Hubbard Realty

Street: 2110 Cloverdale Avenue, Unit 2C

Phone#: (336) 723-0303

City: Winston-Salem

ZIP 27103

County Forsyth

EVALUATION DATA

New: \_\_\_ Change: \_\_\_ Delete: \_\_\_

Date: 4/21/08

Evaluation Type: FCI/CMP

Date: \_\_\_/\_\_\_/\_\_\_

Evaluation Type: \_\_\_\_\_

Inspector ID #: 043

Evaluation Comments:

Complaint investigation – IANOV issued - Docket Number 2008-080

SNC DETERMINATION: If this evaluation resulted in a SNC determination, fill in this block. (NOTE: SNC determinations are SNY/SNN evaluations. The SNY/SNN evaluation can also be submitted later on a separate form.)

Facility is (check one):

\_\_\_\_\_ a SNC (SNY evaluation)

Docket # \_\_\_\_\_

or

\_\_\_\_\_ no longer a SNC (SNN evaluation)

YES / NO CSE ONLY

Waste Involved	Volume	Exposure Medi (a, gw, sw, s)	Distance to Residence	Number of People involved	Distance to On-site wells	Distance to Off-site wells

Date Determined: \_\_\_/\_\_\_/\_\_\_

Branch: \_\_\_\_\_ Person: \_\_\_\_\_

Return to Compliance: \_\_\_/\_\_\_/\_\_\_

DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES

DIVISION OF WASTE MANAGEMENT

HAZARDOUS WASTE SECTION  
ACTIVITY REPORT

Monday, April 21, 2008

=====

**SUBJECT:** Forsyth Hubbard Realty

**REASON FOR VISIT:** Complaint Investigation

**ADDRESS:** 2110 Cloverdale Avenue, Unit 2C

**CITY, STATE, ZIP:** Winston-Salem, NC 27103-2516

**SITE ADDRESS:** 5636 Pine View Dr, Winston-Salem

**BY WHOM:** Ernest Lawrence - Waste Management Specialist

=====

**DATE INVESTIGATION OPENED** 4/21/2008

**TIME SPENT**

=====

**PERSON CONTACTED** Landowner contact person is Harvey Wade

**EPA ID NUMBER** None

**REPORT:**

Mike Settle with Forsyth Environmental Affairs contacted the HWS about a number of abandoned 55-gallon containers at 5636 Pine View Drive in Winston-Salem.

I visited the site on April 21, 2008 with Mike Settle and Rose Pruitt (DWQ). The containers were at an abandoned auto salvage yard that was being cleaned up. The containers had been covered by a large number of scrap tires.

There were approximately seventy-five 55-gallon containers in an area that was an estimated 100 X 100 feet. Many of the containers were in various stages of deterioration, and some of the adjacent soil was discolored due to releases.

Some of the containers were labeled motor oil, antifreeze, or transmission fluid. One container was labeled "Industrial Cleaner." Two containers labeled "Nitromethane 99%" were observed. One of the 55-gallon containers labeled antifreeze had a bulging top.

In a separate area near a mobile home there were nineteen 55-gallon containers on an asphalt driveway. Some of these were labeled transmission fluid or motor oil.

The site had been operated by Randy Moore, Hemrick Auto, 1155 Old Hollow Rd, Winston-Salem, NC 27105 (336-767-1788).

DWQ plans to issue an NOV With Recommended Enforcement that will require a cleanup after approval of a required plan.