



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Table with columns for Unit Type (Lined MSWLF, Closed MSWLF, CDLF), LCID, YW, Transfer, Compost, SLAS, and checkboxes. Includes County: Rockingham, Permit No.: SLAS-79-04, and File Type: COMPLIANCE.

Date of Site Inspection: April 14, 2016 Date of Last Inspection: September 16, 2015

FACILITY NAME AND ADDRESS:

Gann Brothers Septic Tank Service, Inc.
367 Case Road
Madison, North Carolina 27025

GPS COORDINATES: N: 36.40585° W: 80.01926°

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Patrick & Eric Gann
Telephone: (336) 548-2971
Cell Phone (Eric Gann): (336) 520-8680
Email address: gann.brothers@yahoo.com

FACILITY CONTACT ADDRESS:

191 Percy Lane
Mayodan, North Carolina 27027

PARTICIPANTS:

Troy Harrison, Solid Waste Section

STATUS OF PERMIT:

Active
Issued: August 8, 2012
Expires: August 8, 2017

PURPOSE OF SITE VISIT:

Routine Inspection

STATUS OF PAST NOTED VIOLATIONS:

OBSERVED VIOLATIONS:

- 1. 15A NCAC 13B .0838 (a)(18) states: Approved nutrient management plans shall be followed.

Permit number SLAS-79-06/Conditions of Operating Permit Section two states in part: This site shall be operated and maintained in accordance with the nutrient management plan submitted by Patrick and Eric Gann and approved by the Division of Waste Management.

Gann Brothers Septic Tank Service, Inc. was in violation of 15A NCAC 13B .0838 (a)(7) because the approved Nutrient Management Plan (Plan) Section B paragraph 2 states in part: "In order for this fescue field to receive septage, a 80% stand should be maintained". Field 2 appeared to have less than 80% coverage of fescue. The other vegetation was either dormant, dead or damaged at the time of inspection.

In order to come into compliance, Gann Brothers Septic Tank Service, Inc. must immediately follow the nutrient management plan for SLAS-79-04.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

You can also contact the Rockingham County Cooperative Extension at 336-342-8230 for advice on field maintenance and weed control. If another cropping system other than fescue be desired or recommended, a revised Plan, written by a certified technical specialist, reflecting the change must be submitted. Contact Connie Wylie at connie.wylie@ncdenr.gov or 910-433-3352 to update the Plan.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

1. All photographs were taken by Troy Harrison on April 14, 2016.
2. The Septage Land Application Site consists of Field 1 (5.8 acres) and Field 2 (5.6 acres).
3. The site is permitted for land application of domestic septage and grease septage.
4. The site is located at 367 Case Road and has accessible all-weather roads to the septage land application field covered under the permit.
5. Appropriate signage was displayed at the site.
6. Disposal area boundaries were delineated with permanent markers with the exception of the southwest and northeast corners of Field 2 and northeast corner of Field 1.
7. All septage discharges appear to have been made within the disposal area boundary with the possible exception of the southwest corner of Field 2 which is missing the permeant marker.
8. There is no evidence of standing liquid or pooled waste. The waste appeared to be evenly distributed throughout the fields.
9. Dead, damaged or dormant areas & vegetation other than fescue was observed in Field 2.



Northern Section of Field 2

10. No objectionable odors were observed.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 828-296-4701

Troy Harrison
Environmental Senior Specialist
Regional Representative

Sent on: 4/20/2016	<input checked="" type="checkbox"/>	Email	<input type="checkbox"/>	Hand delivery	<input type="checkbox"/>	US Mail	<input checked="" type="checkbox"/>	Certified No. <u>7014 0510 0000 4466 3500</u>
--------------------	-------------------------------------	-------	--------------------------	---------------	--------------------------	---------	-------------------------------------	---

Copies: Tony Gallagher, Composting & Land Application Branch Head
Michelle Sclafani, Composting & Land Application Branch
Connie Wylie, Composting & Land Application Branch