



Waste Management  
ENVIRONMENTAL QUALITY

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

UNIT TYPE:											
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS	<b>COUNTY: Guilford</b> <b>PERMIT NO.: N0730</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** June 14, 2016

**Date of Last Inspection:** April 28, 2016

**FACILITY NAME AND ADDRESS:**

Pearman Quarry Road LCID Landfill  
7612 Pearman Quarry Road  
Kernersville, NC 27284

**GPS COORDINATES:** N: 36.21285 W: -80.01581

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Joel Richardson, Jr., Owner/Operator – Pearman Quarry Road LCID Landfill  
h. 336-643-7214  
c. 336-602-5820  
[jrguide@bellsouth.net](mailto:jrguide@bellsouth.net)

**FACILITY CONTACT ADDRESS:**

Joel Richardson, Jr.  
7612 Pearman Quarry Road  
Kernersville, NC 27284

**PARTICIPANTS:**

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)  
Joel Richardson, Sr. - Pearman Quarry Road LCID Landfill

**STATUS OF PERMIT:**

Land Clearing and Inert Debris Landfill Notification recorded with the Guilford County Register of Deeds May 06, 2008  
Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

**PURPOSE OF SITE VISIT:**

Comprehensive Inspection (to ensure that the notified land clearing and inert debris (LCID) landfill is in compliance with 15A North Carolina Administrative Code (NCAC) 13B .0563, .0564, and .0566)

**STATUS OF PAST NOTED VIOLATIONS:**

None

**OBSERVED VIOLATIONS:**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**

**Division of Waste Management**

**Solid Waste Section**

Page 2 of 3

**ADDITIONAL COMMENTS**

On June 14, 2016, John Patrone met with Joel Richardson, Sr. to conduct a comprehensive inspection of the Pearman Quarry Road LCID Landfill on Pearman Quarry Road in Stokesdale, Guilford County.

1. The Pearman Quarry Road LCID Landfill is a notified land clearing and inert debris (LCID) landfill.
2. The LCID landfill is estimated to be ~ 1 acre.
3. The LCID landfill is open to the general public.
4. It has been stated that the left side of the landfill contains only soil and inert materials.
5. Logs are removed from land clearing debris (LCD) and stored for firewood.
6. Mr. Richardson stated that LCD on site has been received within the last month.
7. The facility has been working across the landfill, from top to bottom. It was stated that the LCD will be moved to create a lift, stepped along the rear side slope, and covered with soil.
8. Per 15A NCAC 13B .0566(3), "Solid waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells."
9. Per 15A NCAC 13B .0566(4), "Adequate soil cover shall be applied monthly, or when the active area reaches one acre in size, whichever occurs first."
10. Side slopes should be graded such that a 3:1 slope ratio is obtained or a ratio of which no indication of erosion or runoff is observed.
11. A ready supply of soil is available on site for cover material.
12. Open burning of solid waste is prohibited.
13. There was no indication of erosion or runoff.
14. The facility has an all-weather access road.
15. The facility is secured by a locked gate.
16. The facility has a proper sign.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 336-776-9673

John Patrone, Environmental Senior Specialist  
Division of Waste Management, NCDEQ

Sent on: June 14, 2016	X	Email		Hand delivery		US Mail		Certified No. [ ]
------------------------	---	-------	--	---------------	--	---------	--	-------------------

Electronic Copies: Deb Aja, Western District Supervisor - SWS  
Jessica Montie, Compliance Officer - SWS

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

Digital pictures taken June 14, 2016  
by John Patrone, DWM – SWS

Notified LCID landfill working face area

