



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Table with columns for Unit Type (Lined MSWLF, Closed MSWLF, CDLF, LCID, HHW, Tire T&P/Collection, YW, White goods, Tire Monofill, Transfer, Incin, Industrial Landfill, Compost, T&P, DEMO, SLAS, FIRM, SDTF) and rows for County (Harnett), Permit No. (SLAS 43-04), and File Type (COMPLIANCE).

Date of Site Inspection: 6/16/2016

Date of Last Inspection: 4/01/2015

FACILITY NAME AND ADDRESS:

Hardee's Septic Tank Service
1061 White Memorial Church Road
Willow Springs, NC 27592

GPS COORDINATES: N: 35.43790 E: -78.71191

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: William Hardee
Telephone: (919) 639-2060
Email address: bill@hardees-septic-tank.com
Fax: (888) 786-6583

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS:

Connie Wylie

STATUS OF PERMIT:

Inactive - permit expires June 7, 2018

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS:

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. This site is officially inactive. No land application has occurred. No land application may occur until the Division has inspected the site for compliance with all permit conditions and the nutrient management plan. The site will also need to be GPS'd and a soil analysis is required per Permit Condition. 2.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 433-3352

Connie S. Wylie
Regional Representative

Sent on:		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	----------	---------	--	-------------------