

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH
FILE TRANSMITTAL & DATA ENTRY FORM**

Your Name: Ernest Lawrence

Facility ID Number: NCD083682526

Facility Name: Bakers Waste Equipment Inc

Document Group: Inspection/Investigation (I)

Document Type: I - Compliance Evaluation Inspection (CEI)

File Description/Comments: No violations

Date of Document: 4/25/2016

Author(s) of Document: Ernest Lawrence

Inspector ID #: NC043

Suborganization: Western Region

County (if not on report): Caldwell



PAT MCCRORY
Governor

DONALD R. VAN DER VAART
Secretary

RCRA INSPECTION REPORT

Facility Address

Bakers Waste Equipment Inc
1808 Norwood St SW
Lenoir NC 28645

Facility Contact – Alex Suarez (asuarez@bwe-nc.com) 800-221-4153

EPA ID Number – NCD083682526

Inspector (s) – Ernest Lawrence

Date of Inspection – April 25, 2016

Date of Previous Inspection – March 10, 2015

Status - SQG

Inspection Type – CEI

Present at Inspection – Alex Suarez, Ernest Lawrence

Facility Description

Bakers Waste Equipment is a manufacturer of refuse containers, including solid waste compactor containers and grease containers for the biofuel industry. The company previously operated at three locations in Burke and Catawba County but has consolidated its operations at the 1808 Norwood St SW facility. This location was previously used by Broyhill Furniture Whitel Plant. The facility opened in October 2013.

The facility has one building on about 28 acres. There are currently 125 employees. Municipal water and sewer is used and the nearest residence is adjacent to the property line.

The facility starts with raw metal and goes through cutting, bending, welding, and painting processes. Four paint booths are used.

Unused paint is filtered and returned to the process as primer for the waste containers. The lines are flushed mostly with paint, but some solvent is used to flush the lines. Used solvent from flushing lines is used to thin darker colors and is used in the primer coat for containers. There was one 55-gallon container in the Chemical Room to collect paint and solvent to be re-used.

Old paint is collected in a 55-gallon container and shipped as hazardous waste. None was on site at the time of inspection.

Wastes Generated

D001, F003, F005 – Paint waste (excess or old paint)

Solvent rags are collected at each spray booth and transferred to a 55-gallon container to be laundered.

Transporters

Spectra – TNR000005439

TSDs

Giant Resource – ALD070513767

Manifests

Filled Out Correctly - Yes

Signed Copies – Yes

LDR Notification Attached - Yes

Storage Area

The facility has an outdoor storage area. There was no waste in the area at the time of inspection.

Containers labeled “Hazardous Waste”? – NA

Containers dated when accumulation began? – NA

Containers compatible with waste? – NA

Containers closed? – NA

Managing incompatible waste? – NA

Containers in good condition and not leaking? – NA

Adequate aisle space – NA

A telephone or two-way radio available at the scene of operation to summon emergency assistance? – Yes

Inspection Records

There was no waste in the storage area.

Emergency arrangements made with fire, police, hospital, and emergency responders? –Example letters were sent to the facility to assist in contacting the hospital, police department, and other responders.

Satellite Accumulation Areas

There are no satellite accumulation areas.

Emergency coordinator on premises or on call at all times? – Yes

Contingency Plan – Information posted next to the telephone

Name and phone number of emergency coordinator? – Yes

Location of fire extinguishers, spill control equipment, and fire alarm? – Yes

Number to the fire department, unless there is a direct alarm? – Yes

Training

The generator has ensured that all employees that are involved with the handling of hazardous waste are thoroughly familiar with proper waste handling and emergency procedures? – Yes

Used Oil

None observed during the inspection.

Site Deficiencies

None



4/25/2016

Copy sent to facility

RCRA Inspector

Date

Facility Contact