

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH
FILE TRANSMITTAL & DATA ENTRY FORM**

Your Name: Heather Goldman

Facility ID Number: NCS000002325

Facility Name: James Gaddy Property

Document Group: Inspection/Investigation (I)

Document Type: I - Complaint Investigation (CMP)

File Description/Comments: Residential Waste. No violations cited.

Date of Document: 6/7/2016

Author(s) of Document: Heather Goldman

Inspector ID #: NC111

Suborganization: Western Region

County (if not on report): Mecklenburg



PAT MCCRORY
Governor

DONALD R. VAN DER VAART
Secretary

MICHAEL SCOTT
Director

Site Violations:

-None

Heather Goldman
Environmental Senior Specialist
DWQ Hazardous Waste Section

Date

ec: Sean Morris, Compliance Western Unit Supervisor
Central Office Files

James Gaddy Property

NCS 000 002 325

Totes stored along fence in back yard of property.

