



Waste Management
ENVIRONMENTAL QUALITY

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<input checked="" type="checkbox"/>	COUNTY: Bladen PERMIT NO.: SLAS 09-07 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 7/08/2016

Date of Last Inspection: 9/22/2015

FACILITY NAME AND ADDRESS:

Singletary Septic Tank Service
P. O Box 782
Bladenboro, NC 28320

GPS COORDINATES: N: 34.49276 E: -78.85363

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Furnie Singletary
Telephone: (910) 648-2228
Email address: singletary@instrstar.net
Fax: (910) 648-6008

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS:

Connie Wylie

STATUS OF PERMIT:

Active – permit expires August 21, 2016

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS:

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. The cropstand appears adequate at this time, but weed control is needed. Mr. Singletary stated that weed control measures were planned in the near future. Cattle were on field 2 during this visit.
2. The field markers appear accurate, but setbacks were not measured at this time.
3. The required sign is posted at the site entrance. The access road is adequate.
4. No sign of land application outside the permitted boundaries.
5. No sign of recent application. No odors noted.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 433-3352

Connie S. Wylie
Regional Representative

Sent on:		Email		Hand delivery	X	US Mail	Certified No. <u> </u>
-----------------	--	-------	--	---------------	----------	---------	-------------------------