



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Table with columns for Unit Type (Lined MSWLF, Closed MSWLF, CDLF) and checkboxes for various waste types (LCID, YW, Transfer, Compost, SLAS, HHW, White goods, Incin, T&P, FIRM, Tire T&P/Collection, Tire Monofill, Industrial Landfill, DEMO, SDTF). Includes a summary box for County (Columbus), Permit No. (SLAS 24-04), and File Type (COMPLIANCE).

Date of Site Inspection: 7/15/2016

Date of Last Inspection: 9/22/2015

FACILITY NAME AND ADDRESS:

S & S Septic Tank Pumping
388 Stancilway Drive
Tabor City, NC 28463

GPS COORDINATES: N: 34.08530 E: -78.74926

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Stephen Stancil
Telephone: (910) 377-2217
Email address: N/A
Fax: N/A

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS:

Connie Wylie

STATUS OF PERMIT:

Inactive – permit expires December 31, 2017

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS:

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. No sign of septage activity. **No land application shall occur until all permit requirements have been met and an inspection has been performed to ensure compliance with all septage management rules and permit conditions.** Field markers and GPS permitted boundaries will have to be verified at that time.
2. Signs are posted at the site entrance and the access road is adequate.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (910) 433-3352

Connie S. Wylie
Regional Representative

Sent on:		Email		Hand delivery	X	US Mail	Certified No. []
----------	--	-------	--	---------------	----------	---------	-------------------