



Waste Management
ENVIRONMENTAL QUALITY

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Columbus PERMIT NO.: SLAS 24-06 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 7/15/2016

Date of Last Inspection: 9/22/2015

FACILITY NAME AND ADDRESS:

PVI Enterprises
P.O. Box 684
Tabor City, NC 28463

GPS COORDINATES: N: 34.10749 E: -78.67874

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: James Faulk
Telephone: (910) 653-3672
Email address: pvienterprises@yahoo.com
Fax: (910) 653-5002

FACILITY CONTACT ADDRESS:

1363 Walter Ward Road
Nakina, NC 28455

PARTICIPANTS:

Connie Wylie

STATUS OF PERMIT:

Active – permit expires May 18, 2017

PURPOSE OF SITE VISIT:

Routine

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS:

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. This site is permitted as one field. There are signs that the site is in use (old spray paths). Noted a honey wagon/tractor on site for land application.
2. The required signs are posted at the site entrance and the access road is adequate.
3. The cropstand appears adequate for land application. No sign of heavy application. **Control weeds and other types of vegetation to maintain the approved cropstand of bermuda.**
4. The field markers appear adequate. No sign of land application outside the permitted boundaries.
5. It appears that the approved setbacks are being met, but setbacks were not measured at this time.
6. No sign of recent application and no odors noted.

Please contact me if you have any questions or concerns regarding this inspection report.

Connie S. Wylie

Phone: (910) 433-3352

 Connie S. Wylie
Regional Representative

Sent on:		Email		Hand delivery	X	US Mail		Certified No. []
-----------------	--	-------	--	---------------	----------	---------	--	-------------------