



Waste Management
ENVIRONMENTAL QUALITY

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID		YW	✗	Transfer	✗	Compost	✗	SLAS		COUNTY: Jackson PERMIT NO.: 50-03-T FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods	✗	Incin		T&P	✗	FIRM		
CDLF		Tire T&P / Collection	✗	Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 4/13/2016

Date of Last Inspection: 2/4/2016

FACILITY NAME AND ADDRESS:

Scott Creek Transfer Station

48 Recycle Pl
Sylva, NC 28779

GPS COORDINATES: N: 35.40155° W: 83.16249°

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Chad Parker, Jackson County Public Works Director

Telephone: (828) 586-2437

Email address: chadparker@jacksonnc.org

FACILITY CONTACT ADDRESS:

Jackson County Solid Waste Department
401 Grindstaff Cove Rd, Suite A-207
Sylva, NC 28779

PARTICIPANTS:

Chad Parker, Public Works Director

Steve Ogle, Transfer Station Supervisor

Lee Hill, NCDEQ - Solid Waste Section

STATUS OF PERMIT:

Permit to Construct issued: March 1, 2000, Permit to Operate issued: February 5, 2002

Permit Amendment issued: April 12, 2013, Permit Expires: February 9, 2019

PURPOSE OF SITE VISIT:

Comprehensive Partial Purpose of Site Visit Follow-Up Other _____

STATUS OF PAST NOTED VIOLATIONS:

15A NCAC 13B .0203(d): Resolved

OBSERVED VIOLATIONS:

None

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

OBSERVED VIOLATIONS:

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

1. All photos were taken by Lee Hill on April 13, 2016.
2. The facility is owned, managed and operated by Jackson County.
3. The service area for the facility is Jackson County.

Operations inspection of Transfer Station (50-03T)

4. The transfer station floor was observed and appeared to be in good condition.
5. The tipping floor drains were clean and appeared to be functioning properly.
6. Construction and Demolition waste was segregated from MSW waste on the tipping floor at the time of the inspection. Construction and Demolition waste is loaded into trailers after a "fluff" layer of MSW is loaded to prevent damage to the floor and sides of the trailer.
7. Windblown waste was well managed and facility staff was actively cleaning windblown material at the time of inspection.
8. No unacceptable waste was observed on the tipping floor at the time of inspection.
9. Loaded trailers are parked on a covered concrete pad with a drainage system to collect any leachate that could occur from parked trailers.

Operations Inspection of Electronic Waste Collection Area

10. Electronic waste is collected at convenience sites and brought to transfer station where the material is consolidated into Gaylord boxes and loaded onto van trailers for shipment.
11. Electronic waste is sent to Powerhouse Recycling in Salisbury, NC.

Beneficial Fill Area

12. The beneficial fill area is located to the east of the scale house.
13. Unapproved material (painted wood and exposed rebar) noted in the February 4, 2016 inspection report had been removed.

Yard Trash/Compost

14. The facility is permitted to receive yard trash and is permitted as a small Type 1 compost facility.
15. The facility was not currently composting at the time of the inspection.

Operations Inspection of Recycling Transfer Building.

16. The facility utilizes the former MSW transfer building for the collection of cardboard and other recyclable materials.
17. Cardboard is collected in the old transfer building and is loaded into open top trailers.
18. Bottles are collected outside in a separate open top trailer located on the south side of the recycling transfer building.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

ADDITIONAL COMMENTS

None

Signature


Lee Hill, Environmental Senior Specialist, 828-296-4700

Name, Title, Phone Number

Sent on: 4/18/2016	X	Email		Hand delivery		US Mail	Certified No. []
---------------------------	---	-------	--	---------------	--	---------	-------------------

Copies: Deb Aja, Western District Supervisor - Solid Waste Section

Jessica Montie, Compliance Officer - Solid Waste Section

Location	Photo 1
<p>4/13/2016 9:37:38 AM</p>  <p>Map data ©2016 Google</p> <p>NOTES</p>	 <p>NOTES Beneficial Fill Area</p>
Photo 2	Photo 3
 <p>NOTES MSW/C&D Tipping Floor</p>	 <p>NOTES Transfer Station Floor Drains</p>
Photo 4	Photo 5
 <p>NOTES Recycling Transfer Building Tipping Floor</p>	 <p>NOTES Electronics Collection Area.</p>