

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Signage present on both sides of the path as you get to the site.
2. Access road well maintained.
3. Markers were present and easily visible.
4. All septage discharges appeared to be within the permitted boundaries of the fields.
5. No thick applications or spot dumps noticed today. Field very wet. Need to watch applications so as to not leave ruts greater than 3 inches in depth.
6. Could see some signs (drill rows) that the small grain had been planted. Could also see some small grain up.
7. No application at time of inspection. pH not checked.
8. No objectionable odors noticed.
9. No change noticed that would affect setback distances.
10. Records not checked.
11. No violations noted today. Field very wet. Watch applications so as to not leave ruts.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: (919) 707-8283.

Chester R. Cobb, Soil Scientist
Division of Waste Management, NCDENR
Regional Representative

Sent on: 2/20/15		Email		Hand delivery	X	US Mail		Certified No. []
------------------	--	-------	--	---------------	---	---------	--	-------------------