



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Table with columns for unit types (Lined MSWLF, Closed MSWLF, CDLF, LCID, HHW, Tire T&P/Collection, YW, White goods, Tire Monofill, Transfer, Incin, Industrial Landfill, Compost, T&P, DEMO, SLAS, FIRM, SDTF) and a box for County (Wilson), Permit No. (SLAS-98-07), and File Type (COMPLIANCE).

Date of Site Inspection: 10/14/15

Date of Last Inspection: 01/15/15

FACILITY NAME AND ADDRESS:

Myrtle Creech
Creech's Septic Tank & Grease Trap Cleaning
8973 Kirby Road
Kenly, NC 27542

GPS COORDINATES: N: 35.59566 E: -78.07491

FACILITY CONTACT INFORMATION:

Name: Myrtle Creech
Address: PO Box 460 - Lucama, NC 27851
Telephone: 252-239-0016
Email address: tcreech23@gmail.com

PARTICIPANTS: Chester Cobb and Donnie Creech

STATUS OF PERMIT: Active EXPIRES: 02/01/16

PURPOSE OF SITE VISIT: Routine

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the previous inspection conducted on 01/15/15.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

AREAS OF CONCERN AND COMMENTS:

- 1) The required signage present at entrance to site.
- 2) Access road is well maintained.
- 3) Markers up and visible for both fields.
- 4) No septage discharges noticed outside of the permitted boundaries for the fields.
- 5) No spot dumps or thick applications noticed.
- 6) No crop issues noted.
- 7) No application at time of inspection. pH not checked.
- 8) No objectionable odors noticed today.
- 9) No change noticed in the area that would affect setback distances.
- 10) Records not checked.
- 11) No violations noticed today. I collected soil samples from both fields.

Please contact me if you have any questions or concerns regarding this inspection report.

 Chester R. Cobb, Soil Scientist
 Division of Waste Management, NCDEQ
Regional Representative

Phone: (919) 707-8283.

Sent on: 07/12/16		Email		Hand delivery	X	US Mail		Certified No. []
-------------------	--	-------	--	---------------	---	---------	--	-------------------