



Waste Management
ENVIRONMENTAL QUALITY

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS	COUNTY: Guilford PERMIT NO.: N0730 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: July 26, 2016

Date of Last Inspection: June 14, 2016

FACILITY NAME AND ADDRESS:

Pearman Quarry Road LCID Landfill
7612 Pearman Quarry Road
Kernersville, NC 27284

GPS COORDINATES: N: 36.21285 W: -80.01581

FACILITY CONTACT NAME AND PHONE NUMBER:

Joel Richardson, Jr., Owner/Operator – Pearman Quarry Road LCID Landfill
h. 336-643-7214
c. 336-803-2195
jrguide@bellsouth.net

FACILITY CONTACT ADDRESS:

Joel Richardson, Jr.
7612 Pearman Quarry Road
Kernersville, NC 27284

PARTICIPANTS:

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)
Joel Richardson, Jr., Owner/Operator – Pearman Quarry Road LCID Landfill

STATUS OF PERMIT:

Land Clearing and Inert Debris Landfill Notification recorded with the Guilford County Register of Deeds May 06, 2008
Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

PURPOSE OF SITE VISIT:

Comprehensive Inspection (to ensure that the notified land clearing and inert debris (LCID) landfill is in compliance with 15A North Carolina Administrative Code (NCAC) 13B .0563, .0564, and .0566)

STATUS OF PAST NOTED VIOLATIONS:

None

OBSERVED VIOLATIONS:

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

ADDITIONAL COMMENTS

On July 26, 2016, John Patrone met with Joel Richardson, Jr. to conduct a comprehensive inspection of the Pearman Quarry Road LCID Landfill on Pearman Quarry Road in Stokesdale, Guilford County.

1. The Pearman Quarry Road LCID Landfill is a notified land clearing and inert debris (LCID) landfill.
2. The LCID landfill is estimated to be ~ 1 acre.
3. The LCID landfill is open to the general public.
4. Mr. Richardson stated that land clearing debris (LCD) on site has been received within the last month.
5. The landfill operates on a downgradient slope.
6. The facility continues to work across the landfill (near the toe of slope) and from top to bottom.
7. During inclement weather material is commonly deposited at the top of the landfill [to be moved to the bottom].
8. Per 15A NCAC 13B .0566(3), "Solid waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells."
9. Per 15A NCAC 13B .0566(4), "Adequate soil cover shall be applied monthly, or when the active area reaches one acre in size, whichever occurs first."
10. Side slopes should be graded such that a 3:1 slope ratio is obtained or a ratio of which no indication of erosion or runoff is observed.
11. Mr. Richardson stated that the left side of the landfill contains only soil.
12. A ready supply of soil is available on site for cover material.
13. There was no indication of erosion or runoff.
14. Logs are removed from LCD and stored for firewood.
15. Wood mulch is stored on the property.
16. Open burning of solid waste is prohibited.
17. The facility has an all-weather access road.
18. The facility is secured by a locked gate.
19. The facility has a proper sign.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 336-776-9673

John Patrone
Environmental Senior Specialist
Regional Representative

Sent on: August 3, 2016	X	Email		Hand delivery		US Mail	Certified No. []
-------------------------	---	-------	--	---------------	--	---------	-------------------

Copies: Deb Aja, Western District Supervisor - SWS
Jessica Montie, Compliance Officer - SWS



Waste Management
ENVIRONMENTAL QUALITY

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

Digital pictures taken July 26, 2016
by John Patrone, DWM – SWS

LCID landfill - view across top



LCID landfill – view from bottom upward (left)



LCID landfill – view from bottom upward (right)



LCID landfill – view across bottom

