



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Table with columns for Unit Type (Lined MSWLF, Closed MSWLF, CDLF) and checkboxes for various waste types (LCID, YW, Transfer, Compost, SLAS, HHW, White goods, Incin, T&P, FIRM, Tire T&P / Collection, Tire Monofill, Industrial Landfill, DEMO, SDTF). Includes County: Guilford, Permit No.: N1082, File Type: COMPLIANCE.

Date of Site Inspection: July 26, 2016

Date of Last Inspection: May 9, 2016

FACILITY NAME AND ADDRESS:

Stokesdale LCID, Inc. Landfill
7719 Pearman Quarry Road
Stokesdale, NC 27310

GPS COORDINATES: N: 36.22368 W: -80.01949

FACILITY CONTACT NAME AND PHONE NUMBER:

Ken Van Derveer, Owner - Stokesdale LCID, Inc. Landfill
h. 336-298-3325
c. 908-229-5693
kennyv20@gmail.com

Andy Roberts, Operator - Stokesdale LCID, Inc. Landfill
h. 336-362-5500
c. 336-548-2044
andyroberts@gmail.com

FACILITY CONTACT ADDRESS:

Ken Van Derveer
6408 Peppermill Drive
Oak Ridge, NC 27310

PARTICIPANTS:

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)
Ken Van Derveer, Owner - Stokesdale LCID, Inc. Landfill (via telephone)

STATUS OF PERMIT:

Land Clearing and Inert Debris Landfill Notification [update] recorded with the Guilford County Register of Deeds June 16, 2016.
Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

PURPOSE OF SITE VISIT:

Comprehensive Inspection (to ensure that the notified land clearing and inert debris (LCID) landfill is in compliance with 15A North Carolina Administrative Code (NCAC) 13B .0563, .0564, and .0566)

STATUS OF PAST NOTED VIOLATIONS:

None



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

OBSERVED VIOLATIONS:

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

On July 26, 2016, John Patrone conducted a comprehensive inspection of the Stokesdale LCID, Inc. Landfill on Pearman Quarry Road in Stokesdale, Guilford County.

1. The Stokesdale LCID, Inc. Landfill is a notified land clearing and inert debris (LCID) landfill.
2. The LCID landfill is estimated to be ~ 1/2 acre.
3. Mr. Van Derveer stated that land clearing debris (LCD) on site has been received within the last month.
4. The facility off-loads material atop the landfill then moves it into place to be covered with soil.
5. Per 15A NCAC 13B .0566(3), "Solid waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells."
6. Per 15A NCAC 13B .0566(4), "Adequate soil cover shall be applied monthly, or when the active area reaches one acre in size, whichever occurs first."
7. Side slopes should be graded such that a 3:1 slope ratio is obtained or a ratio of which no indication of erosion or runoff is observed.
8. Ensure a ready supply of soil is available on site for cover material.
9. There was no indication of erosion or runoff.
10. Logs are removed from LCD and stored for firewood.
11. Open burning of solid waste is prohibited.
12. The facility has an all-weather access road.
13. The facility is secured by a locked gate.
14. The facility has a proper sign.
15. The facility has submitted an updated LCID landfill notification to the SWS. Mr. Van Derveer stated that property information pertaining to the landfill is correct.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 336-776-9673

John Patrone
 Environmental Senior Specialist
 Regional Representative

Sent on: August 3, 2016	X	Email		Hand delivery		US Mail	Certified No. []
-------------------------	---	-------	--	---------------	--	---------	-------------------

Copies: Deb Aja, Western District Supervisor - SWS
 Jessica Montie, Compliance Officer – SWS
 Andy Roberts, Operator - Stokesdale LCID, Inc. Landfill

Digital pictures taken July 26, 2016
by John Patrone, DWM – SWS

LCID landfill – material to be moved and covered w/soil



LCID landfill working face area

