



Waste Management  
ENVIRONMENTAL QUALITY

# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management

### Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	<b>COUNTY:</b> Rowan <b>PERMIT NO.:</b> SLAS-80-01 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 8/3/2016

**Date of Last Inspection:** 6/14/2016

**FACILITY NAME AND ADDRESS:**

Myers Septic Tank Co.  
Briggs Road  
Salisbury, North Carolina 28147

**GPS COORDINATES:** N: 36.67591° W: 80.58016°

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Benny Myers, President  
Todd Myers, Vice-President  
Telephone: (704) 633-3962  
Email address: myersseptic tank@att.net

**FACILITY CONTACT ADDRESS:**

1882 Briggs Road  
Salisbury, North Carolina 28147

**PARTICIPANTS:**

Troy Harrison, Composting & Land Application Branch  
Benny Myers, Myers Septic Tank Co.

**STATUS OF PERMIT:**

Active  
Issued: 12/16/2015  
Expires: 8/1/2020

**PURPOSE OF SITE VISIT:**

Compliance Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS:**

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS**

1. All photographs were taken by Troy Harrison on August 3, 2016.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

2. The Septage Land Application Site consists of Field 1 (2.0 acres) and Field 2 (4.4 acres) for a total of 6.4 usable acres.
3. The site is permitted for land application of domestic septage.
4. The site had accessible all-weather roads to the septage land application field covered under the permit.
5. Appropriate signage was displayed at the site.
6. Both fields had disposal area boundaries that were delineated with permanent markers. The missing markers that were noted in the inspection on 6/14/2016 have been replaced.



Field 1 (on left) and Field 2 (on right)

7. All septage discharges appear to have been made within the disposal area boundary.
8. No evidence of standing liquid or pooled waste was observed. The waste appeared to be evenly distributed throughout the field.
9. In the inspection on 6/14/2016, a small portion of Field 2 appeared damaged with ruts was observed. This has been repaired.



Field damaged with ruts has been repaired

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

- 10. No objectionable odors were observed.
  
- 11. The nutrient management plan appears to have been followed on all fields.

Phone: 828-296-4701

\_\_\_\_\_  
Troy Harrison  
Environmental Senior Specialist  
*Regional Representative*

Sent on: August 5, 2016	X	Email		Hand delivery		US Mail	Certified No. [ ]
-------------------------	---	-------	--	---------------	--	---------	-------------------

Copies: Tony Gallagher, Composting & Land Application Branch Head  
Michelle Sclafani, Composting & Land Application Branch  
Connie Wylie, Composting & Land Application Branch