



Waste Management
ENVIRONMENTAL QUALITY

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS	COUNTY: Tyrrell PERMIT NO.: N0282 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: August 10, 2016

FACILITY NAME AND ADDRESS:

Tyrrell Co. NLCID
Hwy. 94 S.
Columbia, NC 27925

GPS COORDINATES: N: Need to get E: -

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Wesley Hopkins – Tyrrell Co. Emergency Management
Phone: 252-796-4516 – Office - 252-394-6557 - Cell
Email: weshopkins@tyrrellcounty.net

FACILITY CONTACT ADDRESS:

106 Water Street
P.O. Box 449
Columbia, NC 27925

PARTICIPANTS:

John College - DWM
Wesley Hopkins – Emergency Management

STATUS OF PERMIT:

Notified site. No Permit Required.

PURPOSE OF SITE VISIT:

Routine Facility Compliance Inspection.

STATUS OF PAST NOTED VIOLATIONS:

None

OBSERVED VIOLATIONS:

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS:

- 1 – This Facility is under 2 acres in size.
- 2 – Facility is adequately secured by gates and fencing.
- 3 – Site has adequate signage.
- 4 - Waste stored at this facility consist of land clearing waste, inert debris, untreated wood and yard waste.
- 5 - Siting of this Notified LCID appears to meet all buffer requirements.
- 6 - Waste is placed above the seasonal high water table and not disposed of in water.
- 7 – Access roads are in mainly all-weather constructed and maintained. May need to rock area that leads to LCID from main road. See attached picture.
- 8 – Facility has good ground coverage to restrain erosion and keeps silt from leaving the site.
- 9 – Digital Pictures taken. Front gate sign to be captured at next site visit.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 919-268-1524
 Email: john.college@ncdenr.gov

Environmental Senior Specialist
Regional Representative

Sent on: August 16, 2016	X	Email		Hand delivery		US Mail	Certified No. []
--------------------------	---	-------	--	---------------	--	---------	-------------------

Copies: * Andrew Hammonds – Eastern District Supervisor
 * Jessica Montie – Compliance Officer

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3

* Yard Trash, signage and road area mentioned in comment #7. * Small Inert Debris pile.

