

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. The U.S. Government is the owner of the property on which the structural fill project is located. The structural fill was constructed during 2009. The property is located in on the Cherry Point Marine Corps Air Station in Havelock, NC.
2. This project was designed to use approximately 16,000 cubic yards of coal ash generated from the Cherry Point Central Heating Plant as structural fill to reconstruct an impact berm used for live rifle target practice.



Coal ash is being used for fill inside the impact berm (front/range side).

3. No exposed ash was visible at the time of the inspection.
4. No ponded water was observed on the structural fill at the time of the inspection.
5. The impact berm on the front towards the range is being rebuilt. The slope will be revegetated with non-seedbearing vegetation. The backside of the berm is heavily vegetated and maintained as needed.

Please contact me if you have any questions or concerns regarding this inspection report.

Shawn McKee
Environmental Senior Specialist
Regional Representative

Phone: 919-707-8284

Sent on: August 23, 2016		Email: X		Hand delivery		US Mail	Certified No. []
------------------------------------	--	-------------	--	---------------	--	---------	-------------------

Copies: Ellen Lorscheider, Section Chief, Solid Waste Section
Ed Mussler, Permitting Branch Head, Solid Waste Section
Elizabeth Werner, Permitting Hydrogeologist, Solid Waste Section