

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH  
FILE TRANSMITTAL & DATA ENTRY FORM**

**Your Name:** Bradley Bailey

**Facility ID Number:** NCD980842132

**Facility Name:** Ecoflo

**Document Group:** Inspection/Investigation (I)

**Document Type:** I - Focused Compliance Inspection (FCI)

**File Description/Comments:** Commercial TSDF Inspection

**Date of Document:** 3/15/2016

**Author(s) of Document:** Bradley Bailey

**Inspector ID #:** NC21

**Suborganization:** Resident Inspector Program

**County (if not on report):** Guilford



## North Carolina Department of Environmental Quality

## Division of Waste Management

## RESIDENT INSPECTOR REPORT

1) **Facility Information**

ECOFLO  
2750 Patterson Street  
Greensboro, NC

EPA ID# NCD 980842132

Permit Status:  RCRA  
 Air  
 Water

2) **Facility Contact**

Darrel Coble

Arrived: 08:30 AM

Departed: 11:30 AM

3) **Date of Inspection / Inspector**

03-15-16  
Bradley Bailey

Shift:  1st  
 2nd  
 3rd  
 Wkend

4) **Facility Description Changes**

None

5) **Areas of Concentration**

Part "B" Permit Physical Inspection  
Facility Operations  
Labeling

Container Management/Staging  
General  
Aisle Spacing/Dates

6) **Site Deficiencies**

None

Docket #: N/A7) **Recommendations**

50 foot buffer marker needs to be clearly marked on outside of building and designate prohibited items (ignitable/reactive/incompatible) from being placed past that marker iaw D-1(a)(7).

Ensure contingency plan updated to provide description of alarms (general, overfill, etc) G-9 Definitions.

8) **Corrections Since Last Inspection**

None

9) **Referrals to DAQ/DWQ/OSHA**

None

Darrel J. Coble 3/15/16  
Facility Representative Date

Bradley Bailey 15 MAR 2016  
Bradley Bailey - NCDENR Date