

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH
FILE TRANSMITTAL & DATA ENTRY FORM**

Your Name: Anthony Foster

Facility ID Number: NCD980842132

Facility Name: ECOFLO, Inc.

Document Group: Inspection/Investigation (I)

Document Type: I - Focused Compliance Inspection (FCI)

File Description/Comments: No violations/Warning Notice

Date of Document: 6/1/2016

Author(s) of Document: Anthony Foster

Inspector ID #: NC055

Suborganization: Resident Inspector Program

County (if not on report): Guilford

North Carolina Department of Environmental Quality
Division of Waste Management

RESIDENT INSPECTOR REPORT

1) Facility Information

ECOFLO
2750 Patterson Street
Greensboro, NC

EPA ID# NCD 980842132

Permit Status: RCRA
 Air
 Water

2) Facility Contact

Ray Dudley

Arrived: 10:00 AM

Departed: 3:30 PM

3) Date of Inspection / Inspector

6/1/16
Anthony Foster

Shift: 1st
 2nd
 3rd
 Wkend

4) Facility Description Changes

None

5) Areas of Concentration

Part B Physical General Container Management Labeling
Informal Meeting

6) Site Deficiencies

Docket #: N/A

Formal Warning: The following issues were found during the inspection and need to be addressed
Immediately.

1. Five containers of Non-Hazardous waste located in the yard at the rear of the facility were found to be open containers. One container of hazardous waste located in the staging area was found to have an open top.
2. Several containers located in the yard and inside the facility were missing labels or any kind of identification. **All** containers must be labeled to identify its contents.
3. Failure to address these issues **immediately** will result in compliance action.

7) Recommendations/Comments

1. All containers of waste must be closed at all times except when directly working with the containers.
2. Containers with holes cut in the tops containing waste should be over packed until the time of their disposal or transfer.
3. There is a large amount of Non-hazardous waste containers and empty containers located in the yard. This area should be managed in such a way that allows inspection of the waste. It is recommended that the area be cleaned out and waste and empty containers be removed in order to better manage this area.
4. A meeting was conducted with Ray Dudley, Paul McAllister, and Ken Webb to discuss the findings of this inspection and to stress the concern of conditions at the facility.
5. A re-inspection will be conducted to ensure compliance with the permit and all areas of concern.
6. **Reminder:** This is a warning notice and future compliance issues could result in formal compliance action against the facility.

8) **Corrections Since Last Inspection**

None

9) **Referrals to DAQ/DWQ/OSHA**

None

Ray Dudley

6-1-16

Facility Representative

Date

Anthony Foster

6-1-16

Anthony Foster - Resident Inspector

Date