

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH  
FILE TRANSMITTAL & DATA ENTRY FORM**

**Your Name:** Andrew Martin

**Facility ID Number:** NCD061263315

**Facility Name:** Nexeo Solutions

**Document Group:** Inspection/Investigation (I)

**Document Type:** I - Focused Compliance Inspection (FCI)

**File Description/Comments:** TSDF Inspection with comments

**Date of Document:** 8/3/2016

**Author(s) of Document:** Andrew Martin

**Inspector ID #:** NC115

**Suborganization:** Resident Inspector Program

**County (if not on report):** Mecklenburg

North Carolina Department of Environmental  
Quality  
Division of Waste Management

**RESIDENT INSPECTOR REPORT**

EPA ID# NCD061263315

Permit Status:  RCRA  
 Air  
 Water

Arrived: 10:15 am  
Departed: 2:15 pm

Shift:  1st  
 2nd  
 3rd

1) **Facility Information**  
NEXEO Solutions  
3930 Glenwood Drive  
Charlotte, NC

2) **Facility Contact**  
Tim Nightwine

3) **Date of Inspection / Inspector**  
8/3/16  
Andrew Martin

4) **Facility Description Changes**  
None

5) **Areas of Concentration**  
Part "B" Permit      General  
Physical Inspection      Waste Management  
10-day Area      Informal Meeting

Waste Compatibility      Labeling  
Container Management  
Satellite Waste Areas      Profiles


6) **Site Deficiencies**  
None

**Docket #:** N/A

7) **Comments**

- A large spot of bubbled and damaged coating was observed in the bay 3 caustic area. A substance or residue may have caused the coating to become damaged. It is recommended that the facility repair the areas of damaged coating and recoat the area per the specification listed in the permit application.

7) **Follow-up**  
None

  
\_\_\_\_\_  
Facility Representative      8/3/16  
Date  
 8-3-16  
\_\_\_\_\_  
Andrew Martin, QEP- Resident Inspector      Date