

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH
FILE TRANSMITTAL & DATA ENTRY FORM**

Your Name: Andrew Martin

Facility ID Number: NCD061263315

Facility Name: Nexeo Solutions

Document Group: Inspection/Investigation (I)

Document Type: I - Focused Compliance Inspection (FCI) File

Description/Comments: TSDf Inspection with comments

Date of Document: 8/18/2016

Author(s) of Document: Andrew Martin

Inspector ID #: NC115

Suborganization: Resident Inspector Program

County (if not on report): Mecklenburg

North Carolina Department of Environmental
Quality
Division of Waste Management

RESIDENT INSPECTOR REPORT

1) Facility Information

NEXEO Solutions
3930 Glenwood Drive
Charlotte, NC

EPA ID# NCD061263315

Permit Status: RCRA
 Air
 Water

2) Facility Contact

Tim Nightwine

Arrived: 1:30 pm

Departed: 4:30 pm

3) Date of Inspection / Inspector

8/18/16
Andrew Martin

Shift: 1st
 2nd
 3rd

4) Facility Description Changes

None

5) Areas of Concentration

Part "B" Permit General
Physical Inspection Waste Management
10-day Area Informal Meeting

Waste Compatibility Labeling
Container Management
Satellite Waste Areas Profiles

Docket #: N/A

6) Site Deficiencies

None

7) Comments

The floor coatings are being redone in the corrosive storage area.

7) Follow-up

None

J E Chlusa 8/18/16
Facility Representative Date
Andrew Martin 8-18-16
Andrew Martin, QEP- Resident Inspector Date