

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH
FILE TRANSMITTAL & DATA ENTRY FORM**

Your Name: Ernest Lawrence

Facility ID Number: NCR000166991

Facility Name: Altec Industries Inc

Document Group: Inspection/Investigation (I)

Document Type: I – Compliance Evaluation Inspection (CEI)

File Description/Comments: No violations

Date of Document: 8/10/2016

Author(s) of Document: Ernest Lawrence

Inspector ID #: NC043

Suborganization: Western Region

County (if not on report): Surry



PAT MCCRORY
Governor

DONALD R. VAN DER VAART
Secretary

RCRA INSPECTION REPORT

Facility Information

Altec Industries Inc
200 Altec Way
Mt. Airy, NC 27030

Facility Contact

Kenny Badgett 336-504-3355 kenny.badgett@altec.com

EPA ID Number – NCR000166991

Inspector (s) – Ernest Lawrence

Date of Inspection – August 10, 2016

Last Inspection Date – No previous inspection

Status –SQG

Inspection Type -- CEI

Present at Inspection – Kenny Badgett

Facility Description

Altec Industries operates a maintenance facility for the fleet of trucks used by Pike Electric. This includes a shop for paint and body work. There is a large truck repair area that generates used oil and a non-hazardous parts cleaner waste.

| | |
|-----------------------------------|-------------|
| Distance to closest residence | >500 yards |
| Distance to closest off-site well | >1 mile |
| Water supply | City water |
| Sewage | City sewage |
| Operating shifts | 1 |
| Number of employees | 150 |

Wastes Generated

D001, F003, F005 – Hazardous waste liquid

Storage Areas (s) – There were three 55-gallon containers at the time of inspection.

Containers on site for less than 180 days? – Yes

Containers dated when accumulation began? – Yes. (Earliest date May 10, 2016).

Containers labeled “Hazardous Waste?” –One label was added at the time of inspection. The facility must ensure all containers are marked or labeled “Hazardous Waste.”

Containers compatible with waste? – Yes.

Containers closed? – Yes.

Managing incompatible waste? - Yes.

Required Equipment

Internal communications or alarm system that provides emergency instruction to personnel? – Yes.

Fire extinguishers and fire control equipment, spill control and decontamination equipment? – Yes

Satellite Accumulation Area – There was one 5-gallon container inside the spray booth. The facility is currently emptying it immediately whenever waste is added. If the facility wants to accumulate paint waste in the container during the day, it will be necessary to label the container and keep it securely closed.

Additionally, the facility has two 55-gallon containers with an aerosol extraction unit.

Satellite containers were in compliance.

Inspection Records – Yes.

Emergency Coordinator on premises or on call at all times? – Yes.

Emergency arrangements with fire, police and emergency response teams? – Yes.

Manifests – The manifests were reviewed for the past two years.

Filled Out Correctly?– Yes.

Signed Copies?– Yes

LDR Notification Attached?– Yes

Transporters – Clean Safe Technologies MDR000526798

TSDF – Giant Resources -ALD070513767

Contingency Plan – Information posted next to the telephone

Name and phone number of emergency coordinator? – Yes.

Location of fire extinguishers, spill control equipment, and fire alarm? – This was added immediately after the inspection.

Number to the fire department, unless there is a direct alarm? – Yes.

Training

The generator has ensured that all employees that are involved with the handling of hazardous waste are thoroughly familiar with proper waste handling and emergency procedures? – Yes

Universal Waste

None observed.

Used Oil – The facility has a 10,000-gallon underground storage tank for used oil. Used oil is collected in the truck repair area in units that are connected through piping to the storage tank. The piping is labeled “Used Oil.”

Site Deficiencies

No violations were observed.

Comments/Recommendations

- The facility must ensure containers of hazardous waste are marked or labeled.
- The facility must ensure the required emergency information is posted.



8/10/2016

Copy sent to facility

RCRA Inspector

Date

Facility Contact