

**HAZARDOUS WASTE SECTION - COMPLIANCE BRANCH
FILE TRANSMITTAL & DATA ENTRY FORM**

Your Name: Bradley Bailey

Facility ID Number: NCD077840148

Facility Name: Safety-Kleen Archdale

Document Group: Inspection/Investigation (I)

Document Type: I - Focused Compliance Inspection (FCI)

File Description/Comments: Commercial TSDF Inspection- No comments

Date of Document: 9/20/2016

Author(s) of Document: Bradley Bailey

Inspector ID #: NC21

Suborganization: Resident Inspector Program

County (if not on report): Randolph

North Carolina Department of Environmental Quality

Division of Waste Management

RESIDENT INSPECTOR REPORT

- 1) **Facility Information** **EPA ID#** NCD 077840148
 Safety Kleen **Permit Status:** RCRA
 6182 Old Mendenhall Road Air
 Archdale, NC Water
- 2) **Facility Contact** **Arrived:** 10:30 AM
 Phil Curry **Departed:** 11:30 AM
- 3) **Date of Inspection / Inspector** **Shift:** 1st
 09-20-16 2nd
 Bradley Bailey 3rd
 Wkend
- 4) **Facility Description Changes**
 None
- 5) **Areas of Concentration**
 Part "B" Permit Physical Inspection Container Management
 Facility Operations General Permit issued 20MAY2013 to 19MAY2018
- 6) **Site Deficiencies** **Docket #:** N/A
 None
- 7) **Recommendations/Comment**
 Online facility ticket task id 7452696-001 for leaking roof of storage area.
 Main gate for trucks not working properly, technicians scheduled for today
- 8) **Corrections Since Last Inspection**
 None
- 9) **Referrals to DAQ/DWQ/OSHA**
 None



 Facility Representative 9/20/16
Date



 Bradley Bailey - NCDEQ 20 SEP 2016
Date