



Waste Management  
ENVIRONMENTAL QUALITY

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

UNIT TYPE:											
Lined MSWLF		LCID		YW		Transfer	<b>X</b>	Compost		SLAS	<b>COUNTY: Wilson</b> <b>PERMIT NO.: 9808T-TRANSFER-2000</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection: October 05, 2016**

**Date of Last Inspection: February 26, 2016**

**FACILITY NAME AND ADDRESS:**

Waste Industries Black Creek Road Transfer Facility  
3031 Black Creek Road  
Wilson, NC 27893

**GPS COORDINATES:** N: 35.68509 E: -77.90520

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Michael Lee  
Telephone: 252 291 6635 cell 252 885 0201  
Email address: [michael.lee@wasteindustries.com](mailto:michael.lee@wasteindustries.com)  
Fax: 252 243 6460

**FACILITY CONTACT ADDRESS:**

Waste Industries Black Creek Rd. Transfer Facility  
P.O. Box 1831  
Wilson, NC 27893

**PARTICIPANTS:**

Tyrone Sumler – Transfer Station Supervisor  
John College – NCDEQ-DWM

**STATUS OF PERMIT:**

Active. Issued August 04, 2015. Limited Review October 11, 2020. Expires October 11, 2020.

**PURPOSE OF SITE VISIT:**

Comprehensive Facility Compliance Inspection.

**STATUS OF PAST NOTED VIOLATIONS:**

None

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**

**Division of Waste Management**

**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS:**

- 1 - The Permit and Ops Plan were available for review, and were reviewed.
- 2 - The facility takes in, on average, 450-500 tons per day. The facility is permitted to receive as much as 1000TPD.
- 3 - The service area includes the following counties: Duplin, Edgecombe, Frankin, Greene, Halifax, Johnston, Lenoir, Martin, Nash, Northampton, Pitt, Wake, Wayne, and Wilson Counties. Waste must be transported for disposal to either Sampson Co. Permit No. 82-02 or Republic Services Bertie Permit No. 08-03.
- 4 - The operating hours are Monday thru Friday 7:00 AM to 4:00 PM.
- 5 - Facility has proper signage with required information per permit conditions.
- 6 - Waste screening is being conducted periodically and records kept in available 3 ring binder, screening records were up to date and good. The Ops Plan specifies that each load be inspected by a spotter.
- 7 - Fire control is managed by two charged fire extinguishers and has a 2” hose bib in the transfer building.
- 8 - Facility Certified Operators: Ricky Knight, expires March 24, 2018. Pamela E. Price, expires November 13, 2018. Michael R. Lee, expires July 16, 2017. H.A. Austin, expires December 06, 2016. Facility has additional certified operators available if needed.
- 9 - The tipping floor was clean and drainage was working like it should. The new pipe work appears to be functioning good to prevent the prior clogging issues.as mentioned in prior inspection reports.
- 10- Facility has purchased cow waterers to place behind trailers to catch any potential leaks from trailers.
- 11 - Windblown trash appears to be managed very good per the Inspection today.
- 12 - Surface water swell area has been corrected with rip rap to prevent erosion and if functioning well.
- 13 - Empty trailers are stored in front of the tipping floor. Trailer number **1217** (holes) and **3434** (door seal) are in need of repair as to prevent leakage.
- 14 - Full trailers are stored on concrete pad behind the tipping floor. Trailer number **7910** (holes) is in need of repair as to prevent leakage.
- 15 - Facility contracts with CEI for transportation of the MSW to permitted landfills listed above. CEI was notified as to the trailer issues.
- 16 - Digital pictures taken during this inspection.

Please contact me if you have any questions or concerns regarding this inspection report.

  
\_\_\_\_\_

Phone: 919-268-1524  
Email: [john.college@ncdenr.gov](mailto:john.college@ncdenr.gov)

Environmental Senior Specialist  
***Regional Representative***

Sent on: <b>October 07, 2016</b>	X	Email		Hand delivery		US Mail	Certified No. [ ]
----------------------------------	---	-------	--	---------------	--	---------	-------------------

- Copies:
- \* Andrew Hammonds – Eastern District Supervisor
  - \* Jessica Montie – Compliance Officer

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

- **Signage**



**Tipping Floor**



- **Two of the trailers in need of repair.**

