

\*429SERBSF10,627\*

\*429SERBSF10,627\*

Site Name (Subject): SUPERIOR ELECTRO FINISHES

Site ID (Document ID): NCD000006361

Document Name (DocType): Images/Maps/Presentations (IMG)

Report Segment:

Description: Site Photos, 1986 - 1987

Date of Document: 8/19/1987

Date Received:

Box: *Enter SF and # with no spaces* SF10,627

Access Level: PUBLIC

Division: WASTE MANAGEMENT

Section: SUPERFUND

Program (Document Group): SERB (SERB)

Document Category: FACILITY


**Print Report for  
Record**

**Go to New  
Blank Record**

**Go to New Record -  
(default to last  
record values)**


**Delete Record**

Superior Electro Finishes NCD000006361  
Weston, Inc. Site Sampling  
During a site visit on 7-7-97, numerous plastic drums were  
observed through the slats of this wooden shed. Six weeks  
later the shed was found broke into and empty.  
19 August 1987




**SUPERIOR ELECTRO FINISHING: 19 AUGUST 1987**


Superior Electro Finishes  
NCD000006361  
Mr. Lindsay Walker (second from right),  
V.P. of Allied Tool of Kernersville, NC  
19 August 1987



Superior Electro Finishes  
NCD000006361  
Weston TAT sampling site  
19 August 1987



Superior Electro Finishes  
NCD000006361  
Sherman Woodson, left, of Weston Inc.  
19 August 1987



Superior Electro Finishes, Winston-Salem  
8-19-87

Mr. Lindsay Walker (second from rt.)  
- V.P. of Allied Tool of Kernersville, NC.

AUG 1987

AUG 1987

8-19-87

Superior Electro Fin.  
Winston-Salem

AUG 1987

WESTON TAT

Sampling site

AUG 1987

Sherman Woodson, left, of Weston, Inc.

Superior Electro Finishes  
Winston-Salem, NC

AUG 1987

AUG 1987


Superior Electro Finishes  
Winston-Salem

Weston Inc - site sampling  
on 8-19-87.


AUG 1987

During a site visit on 7-7-87,  
numerous plastic drums were observed  
through the slats of this wooden  
shed. Six weeks later the shed was found  
broken into and empty.


Superior Electro Finishes  
NCD000006361  
Leaking tank outside plant  
7 July 1987




Superior Electro Finishes  
NCD000006361  
Old well: unknown whether or not still operable  
7 July 1987



Superior Electro Finishes  
NCD000006361  
Contents of this tank leaked into the ground  
between May '86 and July '87. Dead bird, center.  
7 July 1987



Superior Electro Finishes  
NCD000006361  
Dead vegetation downgradient of leaking tank  
7 July 1987



SUPERIOR ELECTRO FINISHING: 7 JULY 1987

SUPERIOR ELECTRO FINISHES  
WINSTON - SALEM, NC

old well; unknown

whether or not still operable.



Superior Electro Finishes  
Winston - Salem, NC

Dead vegetation downgradient  
of leaking tank



SUPERIOR ELECTRO FINISHING: 20-21 MAY 1986





Superior  
MAY 1986



PROCESSED BY  
**Kodak**  
JUN. 86 A

PROCESSED BY  
**Kodak**  
JUN. 86 A

PROCESSED BY  
**Kodak**  
JUN. 86 A

35mm 135/36  
Kodak  
6711E