



Waste Management
ENVIRONMENTAL QUALITY

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	<input checked="" type="checkbox"/>	COUNTY: Burke PERMIT NO.: SLAS-12-05 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: March 22, 2016 **Date of Last Inspection:** October 14, 2015

FACILITY NAME AND ADDRESS:

Williams Septic Tank Service
Dogwood Vista Road (SR-1514)
Chesterfield, NC

GPS COORDINATES: N: 35.80474° W: 81.59062°

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Marshall and Darlene Williams
Telephone: (828) 728-7116 Home (828) 381-5319 Cell

FACILITY CONTACT ADDRESS:

P.O. Box 546
Hudson, NC 28638

PARTICIPANTS:

Troy Harrison, NC Solid Waste Section

STATUS OF PERMIT:

Active
Permit issued: February 27, 2014
Expires: February 27, 2019

PURPOSE OF SITE VISIT:

Routine Inspection

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS:

N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

- All Photographs were taken by Troy Harrison on March 22, 2016.
- The Septage Land Application Site consists of two fields totaling 6.5 acres with Field 1 (3.1 acres) and Field 2 (3.4 acres).

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

Page 2 of 2

Looking South at Field 2 from Field 1

- 3. The site is permitted for land application of domestic septage and grease septage.
- 4. The site is located on Dogwood Vista Road and has accessible all-weather roads to the septage land application field covered under the permit.
- 5. Appropriate signage was displayed at the site
- 6. Disposal area boundaries were delineated with permanent markers.
- 7. All septage discharges appear to have been made within the disposal area boundary.
- 8. The waste appeared to be evenly distributed throughout the fields with the exception of a small area of Field 2 which had waste from a recent heavy application. As a reminder, septage shall be applied to the surface of the land from a moving vehicle in such a manner as to have no standing liquid or soil disturbance resulting from the waste flow after the discharge is complete.



- 9. The approved Nutrient Management Plan appears to have been followed.
- 10. No objectionable odors were observed.

Please contact me if you have any questions or concerns regarding this inspection report.

Phone: 828-296-4701

Troy Harrison
Environmental Senior Specialist
Regional Representative

Sent on: April 12, 2016		Email		Hand delivery	X	US Mail	Certified No. []
-------------------------	--	-------	--	---------------	----------	---------	-------------------

Copies: Tony Gallagher, Composting & Land Application Branch Head
Michelle Sclafani, Composting & Land Application Branch
Connie Wylie, Composting & Land Application Branch