



Waste Management  
ENVIRONMENTAL QUALITY

# FACILITY COMPLIANCE INSPECTION REPORT

## Division of Waste Management

### Solid Waste Section

**UNIT TYPE:**

Lined MSWLF		LCID	<input checked="" type="checkbox"/>	YW		Transfer		Compost		SLAS		<b>COUNTY:</b> Guilford <b>PERMIT NO.:</b> N0583 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Site Inspection:** 4/28/2016

**Date of Last Inspection:** NA

**FACILITY NAME AND ADDRESS:**

Langley LCID Landfill  
7400 Brooks Bridge Road  
Gibsonville, NC 27249

**GPS COORDINATES:** N.: 36.22139 W.: -79.54677

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: William Brooks Langley, Jr., Owner/Operator  
Telephone: (336) 584-0436  
Telephone:  
Email address: langleyquarry@gmail.com

Name:  
Telephone:  
Telephone:  
Email address:

**FACILITY CONTACT ADDRESS:**

William Brooks Langley, Jr.  
7400 Brooks Bridge Road  
Gibsonville, NC 27249

**PARTICIPANTS:**

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)  
William Brooks Langley, Jr., Owner/Operator - Langley LCID Landfill

**STATUS OF PERMIT:**

Land Clearing and Inert Debris Landfill Notification recorded with the Guilford County Register of Deeds May 15, 2002  
Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

**PURPOSE OF SITE VISIT:**

Comprehensive  Partial  Routine

**STATUS OF PAST NOTED VIOLATIONS:**

None

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**OBSERVED VIOLATIONS:**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**ADDITIONAL COMMENTS**

On April 28, 2016, John Patrone met with William Langley to conduct a comprehensive inspection of the Langley LCID Landfill on Brooks Bridge Road in Gibsonville, Guilford County.

1. The Langley LCID Landfill is a notified land clearing and inert debris (LCID) landfill.
2. The landfill is estimated to be ~ 1/2 acre.
3. The LCID landfill is open to the general public.
4. Mr. Langley removes logs from the land clearing debris (LCD) and stores them separately for firewood and milling.
5. Per 15A NCAC 13B .0566(3), "Solid waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells."
6. Per 15A NCAC 13B .0566(4), "Adequate soil cover shall be applied monthly, or when the active area reaches one acre in size, whichever occurs first."
7. Side slopes should be graded such that a 3:1 slope ratio is obtained or a ratio of which no indication of erosion or runoff is observed.
8. Ensure a ready supply of soil is available on site for soil cover.
9. Open burning of solid waste is prohibited.
10. There was no indication of erosion or runoff.
11. The facility has an all-weather access road.
12. The facility is secured by a locked gate.
13. The facility has a proper sign. It is suggested that the facility identification number is also posted: N0583.
14. The SWS will conduct a follow-up inspection by the end of May 2016 to observe that LCD has been adequately covered with soil.
15. A copy of the land clearing and inert debris landfill notification submitted to the SWS and a copy of the pertinent LCID rules was given to Mr. Langley.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**ADDITIONAL COMMENTS**

NA

\_\_\_\_\_  
Signature

John Patrone, Environmental Senior Specialist, 336-776-9673

Sent on: 5/6/2016	X	Email		Hand delivery		US Mail	Certified No. [ ]
-------------------	---	-------	--	---------------	--	---------	-------------------

Copies:

Deb Aja, Western District Supervisor - SWS

Jessica Montie, Compliance Officer – SWS

Location	Photo 1
<p data-bbox="164 632 233 657">NOTES</p>	 <p data-bbox="797 632 1040 657">NOTES LCID landfill area</p>
Photo 2	Photo 3
 <p data-bbox="164 1188 591 1213">NOTES LCID landfill external side slope view</p>	 <p data-bbox="797 1188 1040 1213">NOTES LCID landfill sign</p>
Photo 4	Photo 5
<p data-bbox="164 1730 233 1755">NOTES</p>	<p data-bbox="797 1730 867 1755">NOTES</p>