



Waste Management
ENVIRONMENTAL QUALITY

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID	<input checked="" type="checkbox"/>	YW		Transfer		Compost		SLAS		COUNTY: Guilford PERMIT NO.: N0646 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 4/28/2016

Date of Last Inspection: NA

FACILITY NAME AND ADDRESS:

Brame LCID Landfill
8735 Warner Road
Kernersville, NC 27284

GPS COORDINATES: N.: 36.20687 W.: -80.02192

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Benjamin Brame, Owner/Operator
Telephone: (336) 420-0003
Telephone:
Email address: benbrame@gmail.com

Name:
Telephone:
Telephone:
Email address:

FACILITY CONTACT ADDRESS:

Benjamin Brame
8735 Warner Road
Kernersville, NC 27284

PARTICIPANTS:

John Patrone, Environmental Senior Specialist - Solid Waste Section (SWS)

STATUS OF PERMIT:

Land Clearing and Inert Debris Landfill Notification recorded with the Guilford County Register of Deeds February 3, 2005
Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

PURPOSE OF SITE VISIT:

Comprehensive Partial Routine

STATUS OF PAST NOTED VIOLATIONS:

None

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

OBSERVED VIOLATIONS:

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

On April 28, 2016, John Patrone conducted a comprehensive inspection of the Brame LCID Landfill on Warner Road in Kernersville, Guilford County.

1. The Brame LCID Landfill is a notified land clearing and inert debris (LCID) landfill.
2. The LCID landfill is estimated to be near 2 acres.
3. The LCID landfill is open to the general public.
4. Per 15A NCAC 13B .0566(3), "Solid waste shall be restricted to the smallest area feasible and compacted as densely as practical into cells."
5. It is suggested that the facility maintain a small working face.
6. Per 15A NCAC 13B .0566(4), "Adequate soil cover shall be applied monthly, or when the active area reaches one acre in size, whichever occurs first."
7. Side slopes should be graded such that a 3:1 slope ratio is obtained or a ratio of which no indication of erosion or runoff is observed. The side slopes appeared to be graded accordingly.
8. Ensure a ready supply of soil is available on site for cover material.
9. Ensure non-compliant material is not stored near the land clearing debris (LCD)/working face.
10. Open burning of solid waste is prohibited.
11. There was no indication of erosion or runoff.
12. The facility has an all-weather access road.
13. The facility is secured by a locked gate.
14. Ensure the facility sign contains contact name and phone number. It is suggested that the facility identification number is also posted: N0646.
15. The SWS will conduct a follow-up inspection by the end of May 2016 to observe that the LCD is adequately covered with soil.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

ADDITIONAL COMMENTS

NA

Signature

John Patrone, Environmental Senior Specialist, 336-776-9673

Sent on: 5/6/2016	X	Email		Hand delivery		US Mail	Certified No. []
-------------------	---	-------	--	---------------	--	---------	-------------------

Copies:

Deb Aja, Western District Supervisor - SWS

Jessica Montie, Compliance Officer – SWS

Location	Photo 1
<p data-bbox="164 632 237 659">NOTES</p>	 <p data-bbox="797 632 1040 659">NOTES LCID landfill area</p>
Photo 2	Photo 3
 <p data-bbox="164 1188 683 1215">NOTES LCID landfill upper level side slope/active area</p>	 <p data-bbox="797 1188 1211 1215">NOTES LCID landfill upper level active area</p>
Photo 4	Photo 5
<p data-bbox="164 1734 237 1761">NOTES</p>	<p data-bbox="797 1734 870 1761">NOTES</p>