

Brownfields Program  
File Room Document Transmittal Sheet

23

Your Name: Shirley Liggins  
Project ID: 0800604049  
Facility Name: V.F. Site  
Document Group: Environmental Assessment (EA)  
Document Type: Other (O)  
Description: Sub-slab samples  
Date of Doc: 6/9/2011  
Author of Doc: Jerry Deakle

**File Room Use Only**

Date Recieved by File Room:

Date Scanned:

Month	Day	Year
7	6	12

0800604049

Scanner's Initials:

*ael*

08006-04-49

**Taber, Lisa**

---

**From:** Jerry Deakle [jerry@deakle.us]  
**Sent:** Thursday, June 09, 2011 10:33 AM  
**To:** Taber, Lisa  
**Subject:** 224 Wilson Park Rd.  
**Attachments:** Sub-slab Soil Results 2011-3-30.pdf

Hi Lisa,

Here is a condensation of the sub-slab soil samples we took at our Statesville property. The sample depths ranged from 2' to 3' below the slab.

We took these samples to hopefully allay concerns of a prospective buyer and intentionally presented the data in this abbreviated form. If and as necessary, we'll write this up in a more technical format with methods, full data package, and etc. Please let me know if you have any questions.


Regards,

Jerry Deakle  
Jerry Deakle & Associates  
4108 Darlington Place  
Raleigh, NC 27612  
Phone 919-782-1703  
Cell 919-618-1929

Sub-slab Sample Results

Sample ID	Tetrachloroethene	Trichloroethene
Sample 1	0.0026 ppm	0.0
Sample 2	0.0027 ppm	0.0
Sample 3	0.00043 ppm	0.0
Sample 4	0.0047 ppm	0.0
Sample 5	0.0003 ppm	0.0003 (j)

j- Between laboratory method detection limit and method reporting limit.



10/28/01 1-140 CH/LRM/TW

806151

**SITE MAP**  
**VF-JANTZEN, INC. FACILITY**  
**STATESVILLE, NORTH CAROLINA**

FIGURE

**1**