

Scanned By	Date	DOC ID	Permit
Backus	05/24/2011	13998	33E



2311 North Main Street  
PO Box 1529  
Tarboro, North Carolina 27886  
252-823-1021 Fax: 252-823-0137

[www.barnhillcontracting.com](http://www.barnhillcontracting.com)

October 27, 2010

Mr. Ben Barnes  
Division of Waste Management  
Solid Waste Section  
P.O. Box 8998  
Rocky Mount, NC 27804

Re: Apco LCID Landfill Closure  
Permit #33-E  
Edgecombe County, NC

Dear Mr. Barnes:

I am writing you in response to your letter dated September 23, 2010 requiring documented closure of Barnhill Contracting Company's Apco Landfill. Enclosed is a letter certifying that the landfill has sufficient cover, along with a copy of the inspection on September 9, 2010. I have also attached two maps for your review. One map shows the overlaid area and hole locations from GPS coordinates on an older aerial photo when the landfill was still active. The other map shows the overlaid area and hole locations from GPS coordinates on a more recent aerial photo, after the landfill had been reclaimed.

Should you require any additional information, please do not hesitate to contact us.

Yours very truly,

BARNHILL CONTRACTING COMPANY

A handwritten signature in black ink, appearing to read 'Jonathan Proctor', is written over the company name.

Jonathan Proctor  
Estimator

Enclosures



2311 North Main Street  
PO Box 1529  
Tarboro, North Carolina 27886  
252-823-1021 Fax: 252-823-0137

[www.barnhillcontracting.com](http://www.barnhillcontracting.com)

October 27, 2010

Mr. Ben Barnes  
Division of Waste Management  
Solid Waste Section  
P.O. Box 8998  
Rocky Mount, NC 27804

Re: Letter of Certification  
Apco LCID Landfill Closure  
Permit #33-E  
Edgecombe County, NC

Dear Mr. Barnes:

This letter is to certify that the LCID Landfill, permit #33-E, is inactive and one foot of cover has been placed over the entire landfill.

On October 27, 2010 Barnhill Contracting augered random holes across the permitted landfill area. The landfill consists of  $\pm 2.7$  acres of covered material and Barnhill tested 17 random locations throughout this area, with each test hole reaching a depth greater than one foot. Sufficient cover was found at each individual location.


Should you require any additional information, please do not hesitate to contact us.


Yours very truly,

BARNHILL CONTRACTING COMPANY



Drew Johnson, P.E.  
Vice President







**FACILITY COMPLIANCE AUDIT REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS		<b>COUNTY:</b> Edgecombe <b>PERMIT NO.:</b> 33E <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Audit:** September 9, 2010**Date of Last Audit:** July 14, 2003**FACILITY NAME AND ADDRESS:**

Barnhill Contracting-Apco Demo Landfill  
 1663 E Northern Blvd  
 Tarboro, North Carolina 27856

**GPS COORDINATES:** N:35.94042      E: 77.52908**FACILITY CONTACT NAME AND PHONE NUMBER:**

Buddy Rose 252 824 8235, cell 252 813 6200 fax 252 824 8276 email: [brose@barnhillcontracting.com](mailto:brose@barnhillcontracting.com)

**FACILITY CONTACT ADDRESS:**

Barnhill Contracting  
 P.O. Box 1529  
 Tarboro, North Carolina 27886

**AUDIT PARTICIPANTS:**

Ben Barnes NCDENR Solid Waste Section  
 Buddy Rose Barnhill Contracting

**STATUS OF PERMIT:**

Expired October 29, 2003

**PURPOSE OF AUDIT:**

To conduct an audit of a closed LCID landfill

**NOTICE OF VIOLATION(S):**

NONE

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE AUDIT REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2


**STATUS OF PAST NOTED VIOLATIONS:**

NONE

**AREAS OF CONCERN AND COMMENTS:**

- 1) The facility has not received any waste since 2003 and is closed and covered.
- 2) The landfill must be closed in accordance with 15A NCAC 13B .0510 and .0566 (5) (6) and (7) as landfill operations have been discontinued. See enclosed closure guidance.
- 3) Verification that the landfill has been covered by one foot of suitable compacted earth must include a map with the boring points located. This should be submitted within 45 days of the receipt of this audit.
- 4) The tract measures 109 acres and the parcel ID is 473969648000.
- 5) The entrance is secured with a locked gate and fencing, the gate was locked at the time of the audit.
- 6) The Letter of Closure documents should be completed, recorded with the Edgecombe Co. Register of Deeds and submitted to the Division within 60 days of the receipt of this audit.

Please contact me if you have any questions or concerns regarding this audit report.



Phone: 252 459 4502 email: [ben.barnes@ncdenr.gov](mailto:ben.barnes@ncdenr.gov)

*Ben Barnes*  
Environmental Senior Specialist  
**Regional Representative**

<b>Delivered on :</b> September 13, 2010 <b>by</b>		Hand delivery	<b>X</b>	email		Certified No. [ ]
--	--	---------------	----------	-------	--	-------------------

cc: Mark Poindexter, Field Operations Branch Supervisor  
Dennis Shackelford, Eastern District Supervisor  
Donald Herndon, Compliance Officer  
Wendy McNeil, Solid Waste Section Secretary

**FACILITY COMPLIANCE AUDIT REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3



View of the closed landfill standing on the old haul road and facing north west.



View of the closed landfill standing on the old haul road and facing north west.



View of the landfill standing on the old haul road and facing north west.