LCID N41 Com B-N-B Landfill

NC DEPARTMENT OF ENVIRONMENT, HEALTH AND NATURAL RESOURCES

Division of Solid Waste Management

Solid Waste Section

SOLID WASTE MANAGEMENT FACILITY EVALUATION REPORT

Type of Facility LCID Permit # 41-90-20 County GUILFORD

Name of Facility B+B LANDFILL Location 4035 VIEWMONT DR GREENSBORO, N.C. 27406

Date of Last Evaluation _____

I. Permit Conditions Followed ✓ Yes ____ No ____ N/A

A. Specific Condition(s) Violated N/A

II. Operational Requirements Followed ✓ Yes ____ No

15A N.C. Admin. Code 13B Section _____

A. Specific Violation(s) by number and letter.

III. Other Violations of Rule or Law N/A

IV. Evaluator's Comments NEED TO PULL BACK FILL IN NORTHEASTERN CORNER BY CREEK BED AND ALONG NORTH SLOPE NEAR WET AREA IN CREEK BOTTOM. AREA BELOW OLD DAM MAY NEED TO BE PULLED BACK FOR PREPARATION OF FINAL SLOPE.

V. Continuation Page Required? ✓ Yes ____ No Receiving Signature Robert S. Kelly

Evaluation Date 3/26/96 Solid Waste Section [signature]

DEHNR 3793 (Part I White: Facility Part II Canary: Central Office Part III Pink: Regional Office)

Solid Waste Section (Review 7/94)

[signature]

FACILITY EVALUATION REPORT
CONTINUATION PAGE

Permit # 41-90-20

Evaluation Date 3/26/96

I. Permit Condition(s) Violated:

A. Specific Condition(s) Violated

II. Operational Requirements Followed

A. Specific Violation(s) by number and letter.

III. Other Violations of Rules or Law

IV. Evaluator's Comments ALL OTHER AREAS HAVE BEEN PULLED BACK IN PREPARATION FOR FINAL SLOPE. LANDFILL PERSONNEL NEED TO SCREEN FILL FOR ACCEPTABLE WASTE ONLY