Scanned by Grot | Date 04/28/2010 | Doc ID # 10849

JOYCE ENGINEERING, INC.
Waste Industry Experts

Joyce Engineering, Inc
2211 W. Meadowview Road
Suite 101
Greensboro, NC 27407

tel: 336/323-0092
fax: 336/323-0093

www.JoyceEngineering.com

SOLID WASTE SECTION RECEIVED APR 28 2010

April 26, 2010

Mr. Geoffrey Little, P.E.
Permitting Engineer
DENR Division of Waste Management, Solid Waste Section
1646 Mail Service Center
Raleigh, NC 27699-1646

RE: Coble's Sandrock, Inc. C&D Landfill, Permit No. 01-05, Phase 3A Construction – Geologist Inspection.

Dear Geoffrey,

On behalf of Coble's Sandrock, Inc. Joyce Engineering, Inc. is submitting this geologist inspection for the Phase 3A construction at the Coble's Sandrock C&D landfill in response to Rule .0540 Construction Requirements for C&DLF Facilities.

On March 17, 2010 Hannu Kemppinen, P.G. (NC#1490) conducted an inspection of Phase 3A subgrade. On this day the Phase 3A grades exhibited no unusual geologic conditions that would adversely affect the design, construction or operation of the unit. After review of the subgrade survey it appears that the grading has been prepared in accordance with the design.

It is my belief that the Phase 3 subgrade was prepared in accordance with Rule .0540(5) certification requirements.

Sincerely,
JOYCE ENGINEERING, INC.

Hannu Kemppinen

Hannu Kemppinen, P.G.
Senior Project Consultant

C: Coble's Sandrock, Inc.