



FACILITY COMPLIANCE AUDIT REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS		COUNTY: COLUMBUS PERMIT NO.: 24-01 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Audit: July 8, 2010

Date of Last Audit: June 17, 2009

FACILITY NAME AND ADDRESS:

Columbus County LCID Landfill
 107 Landfill Road
 Whiteville, North Carolina 28472

GPS COORDINATES: **N:** 34.29330 **W:** 78.75123

FACILITY CONTACT NAME AND PHONE NUMBER:

Wade Jernigan
 (910) 640-1988

FACILITY CONTACT ADDRESS:

Mr. Mike Loyd
 Waste Management
 251 New Hope Road
 Wellford, South Carolina 29385

Mr. Kip McClary, Public Utilities Director
 Columbus County
 612 North Madison Street
 Whiteville, North Carolina 28472

AUDIT PARTICIPANTS:

Wes Hare, NCDENR - Solid Waste Section
 Wade Jernigan, Waste Management – Site Manager

STATUS OF PERMIT:

< 2 acre unit
 Permit under review.

PURPOSE OF AUDIT:

Comprehensive Audit

NOTICE OF VIOLATION:

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

STATUS OF PAST NOTED VIOLATIONS:

None

FACILITY COMPLIANCE AUDIT REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

AREAS OF CONCERN AND COMMENTS:

1. The LCID is a unit of the closed MSWLF and an expanded permit is currently under review.
2. The LCID is operated by Waste Management for the County (owner).
3. Waste Management will need to keep a copy of the Permit and Operations Plan on-site to insure proper operations and audits.
4. The hours of operation are Mon -Fri: 7:30 AM – 4:00 PM and Sat: 8:00 – 12:00 PM
5. The site is secured with a gate at the entrance and has controlled access for safety
6. No unacceptable waste was noted during the visit.
7. There were several gullies on the slopes. These will need to be repaired to prevent further erosion and potential exposure of debris.
8. The incidental waste items are being removed and placed in a roll-off container for proper disposal.
9. The perimeter slopes need to be maintained at 3:1 slope or flatter. Some of the slopes appear to be steeper than a 3:1 slope. Be sure when covering debris and/or contouring that the slopes are maintained as required. It is noted that grading work and mowing is scheduled for this week. Adequate ground cover will need to be provided within 30 days of grading activities if the area(s) will not be active before the 30 days. Temporary seeding will be required as a minimum.
10. Digital photos were taken during the audit.
11. **Corrective actions are necessary as a result of this audit at this facility and should begin immediately.**



Container near the working face.



Small working face.



Finger washing beginning on the North slope.



Sediment deposit and staining at the toe of the North slope.

FACILITY COMPLIANCE AUDIT REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3

Please contact me if you have any questions or concerns regarding this audit report.



Phone: 910.796.7405

Wes Hare
Environmental Senior Specialist
Solid Waste Section
Regional Representative

Delivered on: <u>July 9 2010</u> by:	Hand delivery	<input checked="" type="checkbox"/>	E-Mail	Certified No.
--------------------------------------	---------------	-------------------------------------	--------	---------------

cc: **Mark Poindexter, Field Operations Branch Head**
Dennis Shackelford, Eastern Regional Supervisor
Donald Herndon, Compliance Officer
Kip McClary, Columbus County Utilities Director