



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer	<input checked="" type="checkbox"/>	Compost		SLAS	<b>COUNTY: Forsyth</b> <b>PERMIT NO: 34-16T</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** May 31, 2012

**Date of Last Inspection:** May 12, 2011

**FACILITY NAME AND ADDRESS:**

Overdale Road Transfer Station  
 5000 Overdale Road  
 Winston-Salem, North Carolina 27101

**GPS COORDINATES:** N: 36.03323    W: 80.23202

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Name: Mark Bacon, General Manager  
 Telephone: (336) 724-0842 (o) or (336) 714-4300 (m)  
 Email address: [baconm@repsrv.com](mailto:baconm@repsrv.com)  
 Fax: (336) 724-0412

**FACILITY CONTACT ADDRESS:**

Mark Bacon, General Manager  
 Republic Services of North Carolina, LLC  
 2875 Lowery Street  
 Winston-Salem, North Carolina 27107

**PARTICIPANTS:**

Mark Tabaczynski, Division Manager, Republic Services of North Carolina, LLC  
 Charles Gerstell, NCDENR-Solid Waste Section

**STATUS OF PERMIT:**

A Permit to Operate a Transfer Facility was issued to Republic Services of North Carolina, LLC on September 13, 2007. The permit shall be subject to review in accordance with 15A NCAC 13B .0201(e) on or before September 13, 2012.

**PURPOSE OF SITE VISIT:**

Comprehensive Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

N/A

**OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 3


**ADDITIONAL COMMENTS**

1. The facility is owned by Republic Services of North Carolina, LLC.
2. The transfer station operation and hauling is contracted to K.R. Drenth Trucking, Inc.
3. The facility currently accepts approximately 400 tons of municipal solid waste each operating day.
4. The permit and operations plan were current and available for review upon request.
5. Waste screening reports were reviewed. Facility staff performed an one waste screening each operating day as outlined in the approved operations plan. The reports appeared adequate.
6. Transfer Station Operations Specialists:
  - Lamard D. Crawford (expires 3/13/12)
  - Daniel Scott Gilbert (expires 11/29/13)
  - Sandra G. Lucas (expires 6/16/12)
  - Franklin May (expires 4/14/12)
  - Jacquelyn N. Posey (expires 6/13/14)
  - Joseph E. Prestandrea (expires 4/15/14)
  - Larry L. Sansbury (expires 12/14/12)
  - Darryl Stratton (expires 2/27/12)
  - Mark Tabaczynski (expires 1/1/15)
7. The facility had proper signage.
8. A gate was provided at the entrance to the facility to prevent unauthorized access when the facility is not in operation.
9. Two motorcycle tires were observed within the waste located on the tipping floor during the inspection. However, these tires were removed from the waste stream by Mr. Crawford and placed to the side for proper disposal. Please continue efforts to remove unacceptable waste streams as they are observed. Your attention to this matter is appreciated.
10. Rebar has been exposed within the tipping floor at the northeast corner of the facility adjacent to the trailer loading area. It is recommended that steps be taken to repair this area to prevent further degradation of the concrete floor.
11. The east wall of the transfer station was in need of cleaning. Pressure-washing is recommended. Remaining walls within the facility were free from heavy buildup of residue.
12. A significant amount of waste was located on the floor of the transfer trailer loading bay and on top of the structural beams along the wall in the loading bay during the inspection. Please ensure that all waste in these areas is picked up and properly disposed of at the end of each operating day. Mr. Tabaczynski stated that waste in these areas is picked up at the end of the working day.
13. Fire extinguishers were available in case of fires at the facility.
14. Windblown waste was well controlled at the time of inspection.
15. Bait boxes were installed along the perimeter of the facility for vector control.
16. The split seam in the exterior wall of the facility adjacent to the transfer trailer loading area has been repaired as requested on the last inspection report. A new piece of steel has been placed over the split seam.
17. As stated under "Status of Permit," the permit is subject to review on September 13, 2012. Mr. Tabaczynski stated that a permit amendment for continued operation was being prepared for submittal.
18. A bag of waste was observed on the ground adjacent to the transfer trailer storage area on the south side at the time of inspection. Please ensure that this waste is picked up and properly disposed of.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 3 of 3

Please contact me if you have any questions or concerns regarding this inspection report.

  
Charles T. Gerstell  
Environmental Senior Specialist  
*Regional Representative*

Phone: (704) 235-2144

Sent on: <u>6/4/12</u>	<input checked="" type="checkbox"/>	Email	<input type="checkbox"/>	Hand delivery	<input type="checkbox"/>	US Mail	<input type="checkbox"/>	Certified No. <input type="checkbox"/>
------------------------	-------------------------------------	-------	--------------------------	---------------	--------------------------	---------	--------------------------	--

Copies: Jason Watkins, Western District Supervisor  
Mark Tabaczynski, District Manager, Republic Services of North Carolina, LLC (electronic copy)