



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS	COUNTY: HARNETT PERMIT NO.: 43-D FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Inspection: October 7, 2011 **Date of Last Inspection:**

FACILITY NAME AND ADDRESS:

Bryant Grading LCID Landfill
 376 Spence Mill Road
 Fuquay-Varina, North Carolina 27526

GPS COORDINATES: N: 35.529275 E: -78.819913

FACILITY CONTACT NAME AND PHONE NUMBER:

Chester Bryant, Bryant Grading & Landfill, Inc., Owner & operator
 (919) 552-3420 (landfill)
 (919) 427-7773 (office)

FACILITY CONTACT ADDRESS:

Bryant Grading & Landfill, Inc.
 305 Spence Mill Road
 Fuquay-Varina, North Carolina 27526

PARTICIPANTS:

Wayne Bryant, Bryant Grading & Landfill, Inc.
 Robert Hearn, Solid Waste Section

STATUS OF PERMIT:

Original Permit to Construct Cell 1, Phases 1-5 issued: December 18, 2000
 Original Permit to Operate Cell 1, Phases 1-5 issued: April 16, 2001
 Amendment No. 1, PTC/PTO, Cell 2 Expansion issued: December 19, 2006
 Permit expires: April 16, 2011
 Permit renewal application currently under review

PURPOSE OF SITE VISIT:

Partial inspection

STATUS OF PAST NOTED VIOLATIONS:

(none)

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 3


OBSERVED VIOLATIONS:

(none)

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS:

1. Visited facility and met with Mr. Bryant; toured site and discussed landfill operations and maintenance. Disposal operations are currently underway in Phase 2, on the western portion of the landfill. Waste reduction operations and a landscape supply yard also exist at this site.
2. Observed appropriate waste types in the landfill disposal area.
3. Observed that the current, active working-face area was an appropriate and manageable size.
4. Observed that current disposal area had adequate soil cover at the time of inspection. Also observed that a soil pile was staged adjacent to the working face area for use as cover soil.
5. Observed that a perimeter drainage ditch marks the limits of the landfill on its north, west, and south sides.
6. Observed piles of mulch-type wood material at the west end of the Phase 2 area. Mr. Bryant explained that this material was being temporarily stored there and that he expected it would be removed within the next few months. Also observed soil, reclaimed inert debris, and equipment stored atop the landfill.



North views of working face area with cover soil staged at right, and stored mulch material visible at left.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3

Please contact me if you have any questions or concerns regarding this inspection report.

Robert Hearn

Phone: (919) 707-8292

Robert Hearn
Environmental Senior Specialist
Regional Representative

Copies: Dennis Shackelford, Eastern District Supervisor
Shawn McKee, Environmental Senior Specialist

Sent on: 2/24/12		Email		Hand delivery	x	US Mail		Certified No. []
------------------	--	-------	--	---------------	---	---------	--	-------------------

