



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

| | | | | | | | | | | | | |
|--------------|--|-----------------------|--|---------------|--|---------------------|-------------------------------------|---------|--|------|--|--|
| Lined MSWLF | | LCID | | YW | | Transfer | <input checked="" type="checkbox"/> | Compost | | SLAS | | COUNTY: Lenoir PERMIT NO.: 54-08T FILE TYPE: COMPLIANCE |
| Closed MSWLF | | HHW | | White goods | | Incin | | T&P | | FIRM | | |
| CDFL | | Tire T&P / Collection | | Tire Monofill | | Industrial Landfill | | DEMO | | SDTF | | |

Date of Site Inspection: October 13, 2011 **Date of Last Inspection:** January 19, 2011

FACILITY NAME AND ADDRESS:

Onslow Container Service,
P.O. Box 9
Deep Run, NC 28525
NCSR 1511/ Bland Howell Rd.

GPS COORDINATES: N: 35.17373 W: 77.69637

FACILITY CONTACT NAME AND PHONE NUMBER:

Al Hill, Owner 252 527 5040 Fax 252 523 0651
Email: ahill@onslowcontainer.com

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS:

Wes Hare, NCDENR Solid Waste Section

STATUS OF PERMIT:

Issued July 7, 2011; Expires December 19, 2016

PURPOSE OF SITE VISIT:

Comprehensive Audit

STATUS OF PAST NOTED VIOLATIONS:

Not Applicable

OBSERVED VIOLATIONS

None

ADDITIONAL COMMENTS

1. The service area for this facility is Craven, Duplin, Lenoir, Pitt and Wayne Counties.
2. The facility is taking an average of 150 tons of waste per day.
3. The wind blown was minimal and is being managed well.
4. The signage at the front gate is as required.
5. The tipping floor is washed with a hot water pressure washer.
6. Fire extinguishers are inside the transfer station and were reading a full charge.
7. Lead acid batteries, white goods, and tires are not accepted at this facility.
8. The waste is being transferred to Republic in Bertie County.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

- 9. Leachate is currently being collected in a 1,500 gallon tank and pumped as needed. The leachate is hauled to the City of Kinston's WWTP for proper disposal.
- 10. All access roads are paved with no erosion problems.
- 11. The facility is very well managed.
- 12. Camera malfunction did not allow for photographs. See earlier audit reports for reference.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 910.796.7405

Wes Hare
Environmental Senior Specialist
Regional Representative

| | | | | | | | | |
|-------------------|---|-------|--|---------------|--|---------|--|-------------------|
| Sent on: 10/14/11 | X | Email | | Hand delivery | | US Mail | | Certified No. [] |
|-------------------|---|-------|--|---------------|--|---------|--|-------------------|

Copies: * Dennis Shackelford, Eastern District Supervisor
 * Shawn McKee, Compliance Officer