



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID	X	YW		Transfer		Compost		SLAS		COUNTY: Wilson PERMIT NO.: N0403 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: November 3, 2011 **Date of Last Inspection:** August 9, 2011

FACILITY NAME AND ADDRESS:

L&L Landfill
 4468 London Church Rd.
 Wilson, North Carolina

GPS COORDINATES: N: 35.79740 E: 77.90734

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Johnnie Langley
 Telephone: 252 304 6149 Johnnie Langley, 252 245 0098 Ronnie Langley
 Email address: langldsc@gmail.com Ronnie Langley
 Fax: 252 281 1007

FACILITY CONTACT ADDRESS:

Johnnie Langley 3009 Anderson Rd. Wilson, North Carolina 27893	Langley's Landscaping & Lawn Care, website: langleyslandscaping.com 3010 Heard Rd Wilson, North Carolina 27896
--	---

PARTICIPANTS:

Ben Barnes NCDENR, Solid Waste Section
 Johnnie Langley, L&L Landscaping
 Ronnie Langley, Langley's Landscaping & Lawn Care

STATUS OF PERMIT:

Notified site, no permit required

PURPOSE OF SITE VISIT:

Follow up audit to determine compliance with NOV dated January 26, 2010

STATUS OF PAST NOTED VIOLATIONS:

15A NCAC 13B .0566 *Resolved*, the slopes have been covered with soil

OBSERVED VIOLATIONS

NONE


The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 3

- 1) The boundary of the landfill footprint needs to be staked to prevent the disposal area from exceeding the 2 acre size limit.
- 2) The slopes need to be graded and stabilized with seed or mulch.
- 3) The access road was well maintained.
- 4) There is a cable across the entrance that was open at the time of the audit.

Please contact me if you have any questions or concerns regarding this inspection report.



Phone: 252 4594502 email ben.barnes@ncdenr.gov

Ben Barnes
Environmental Senior Specialist
Regional Representative

Sent on: November 28, 2011 By	X	Email		Hand delivery	X	US Mail	Certified No. []
----------------------------------	---	-------	--	---------------	---	---------	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor



Covered slope on the eastern side of the LF

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 3



Covered slope on the south eastern side of the LF



Covered slope on the north south eastern side of the

LF



Top of the landfill