



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID		YW	X	Transfer	X	Compost		SLAS	COUNTY: Currituck PERMIT NO.: 2703T FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods	X	Incineration		T&P		FIRM	
CDLF		Tire T&P / Collection	X	Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: January 23, 2013 Date of Last Inspection:

FACILITY NAME AND ADDRESS:

Currituck County Transfer Station
 216 Airport Rd.
 Maple, North Carolina 27956

GPS COORDINATES: N: 36.39700 E: 76.00140

FACILITY CONTACT NAME AND PHONE NUMBER:

Name:	Brenda McQueen	Stacey R. Bowen
Telephone:	(o) 252 232 2504 (c) 252 599 0673	(c) 252 943 3702
Email address:	Brenda.McQueen@CurrituckCountyNC.gov	
Fax:	252 232 3298	

FACILITY CONTACT ADDRESS:

Brenda McQueen	Stacey R. Bowen
Currituck County Public Works	Bowen Company, Inc.
PO Box 38	P.O. Box 394
Currituck, NC 27929	Belhaven, NC 27810

PARTICIPANTS:

Ben Barnes NCDENR-Solid Waste
 Brenda McQueen Currituck Co. Public Works Director

STATUS OF PERMIT:

Active, permit issued on December 12, 2008 and due for review on or about December 12, 2013. No later than July 12, 2013 the operator must submit a request for permit review to the Division.

PURPOSE OF SITE VISIT:

Comprehensive inspection

STATUS OF PAST NOTED VIOLATIONS:

NONE

OBSERVED VIOLATIONS

NONE

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 4

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

1. The normal operating hours are 8am to 4:15 M-S from May 1 to September 30. The rest of the year Saturday's hours are 8am to 12pm
2. The service area is Currituck County and all communities within the county.
3. Waste from the facility is transported to East Carolina Regional Landfill permit # 08-03 in Bertie Co. NC.
4. Scrap tires, yard waste and white goods collection sites are located within the facility.
5. White goods need better management. **Freon containing white goods should be stacked neatly and marked for Freon removal.** Freon removal is being handled by Murky Waters Shawboro, NC.
6. Yard waste facilities shall follow the time and temperature requirements listed in 15A NCAC 13B .1406(10) for all yard trash feed stocks. The temperature requirements include the compost process being maintained at or above 55 degrees Celsius (131 degrees F) for 3 days and aerated to maintain elevated temperatures. Yard trash is defined within 130A-290(a)(45) as solid waste consisting solely of vegetative matter resulting from landscaping maintenance. Leaves from landscaping maintenance and grass clippings are considered yard trash.
7. Scrap tires are being stored in trailers.
8. The grounds were generally clean, but some cleaning needs to be done around the trailer loading area.
9. **Repairs are needed to the walls, insulation is peeling off of the roof and should probably be removed.**
10. Two of the overhead lights need to be replaced.
11. The ventilation fans were tested and work properly.
12. Fire suppression is by three fire extinguishers all charged and a one inch hose bib.
13. According to the Ops Plan waste is to be screened as the waste is dumped on the tipping floor.
14. The tipping floor is to be cleaned at the end of each operating day. The Ops plan indicates that wash water will be swept towards the floor drains in the lower level of the facility. Leachate is held in holding tanks and pumped out as needed.
15. Signage is adequate but **signs need some repair.**
16. **No later than July 12, 2013 the operator must submit a request for permit review to the Division.**

Please contact me if you have any questions or concerns regarding this inspection report.

Ben Barnes

Phone: 252 459 4502 email: ben.barnes@ncdenr.gov

Ben Barnes
 Environmental Senior Specialist
Regional Representative

Sent on: February 4, 2013	X	Email		Hand delivery		US Mail	Certified No. []
---------------------------	---	-------	--	---------------	--	---------	-------------------

Copies: Dennis Shackelford, Eastern District Supervisor
 Jessica Monte, Compliance Officer

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 3 of 4



Inside of building, insulation is deteriorating, the floors are generally clean and in good shape



Small amount of blown waste, wall needs some repair



Freon containing white goods should be stacked upright and marked for Freon removal. White goods are stored on concrete pad.

