LCID	State of North Carolina Department of Environment and Natural Resources Division of Waste Management	**LAND CLEARING & INERT DEBRIS LANDFILL** Facility Annual Report For the period of **July 1, 2011-June 30, 2012**

According to (G.S. 130A-309.09D(b)) completed forms must be returned by August 1, 2012 and a copy of this report must be sent to the County Manager of each county from which waste was received. If you have questions or require assistance in completing this report, contact your Regional Environmental Senior Specialist.

Facility Name: Barnhill Contracting LCID Landfill Permit: 33F-LCID- ID: P1017

Facility Website (URL):

Physical Address		Mailing Address	
Street 1: 10826 HWY 97		Street 1: PO Box 1529	
Street 2:		Street 2:	
City: Rocky Mount	County: Edgecombe	City: Tarboro	
State: North Carolina	Zip: 27801	State: North Carolina	Zip: 27886

Primary Facility Contact Person			Billing Contact Person		
Name: Buddy Rose			Name: Jonathan Proctor		
Phone: (252) 813-6200	Fax: (252) 823-0137		Phone: (252) 823-1021	Fax: (252) 823-0137	
Email: brose@barnhillcontracting.com			Email: jproctor@barnhillcontracting.com		

1. Tipping Fee: $ per N/A

   Tipping Fee: $ per N/A

   Tipping Fee: $ per N/A

2. Estimate the amount of waste taken in an average week at this facility? 200 ☐ tons ☒ cubic yards

3. How many weeks did you operate this year? 40

4. What are the hours/days of operation for this facility? 6:30 AM TO 6:30 PM Monday thru Saturday

5. What is the acreage of the footprint of the waste on site as of June 30? 10.66 Acre(s)

6. Did your facility stop receiving waste during this past Fiscal Year? ☐ Yes ☒ No

   If so, please report the date this occurred:

REMINDER: According to (G.S. 130A-309.09D(b)), this report must be sent to the Regional Environmental Senior Specialist for your area and a copy of this report must be sent to the County Manager of each county from which waste was received.

Please return your completed report to:

Ben Barnes
PO Box 8998
Rocky Mount, NC 27804-6998
phone: 252.459.4502 email: Ben.Barnes@ncdenr.gov

CERTIFICATION: I certify that the information provided is an accurate representation of the activity at this facility.

Signature: Date: Jul 26, 2012

Name: Jonathan Proctor Title: Estimator

Phone Number: (252) 823-1021 Email: jproctor@barnhillcontracting.com

NC DENR
Division of Waste Management - Solid Waste Section

Risk Assessment Form

Facility Name: Barnhill Contracting LCID Landfill Permit: 33F-LCID-

Address: 10826 HWY 97

City: Rocky Mount State: North Carolina Zip: 27801

Person completing Assessment: Jonathan Proctor Date: Jul 26, 2012

Phone Number: (252) 823-1021 Fax: (252) 823-0137 Email: jproctor@barnhillcontracting.com

Instructions:	Please indicate either *Yes or No* for each Receptor and Post Closure Maintenance question. Then please determine the distance or distances for each Receptor from the *Edge of Waste* (using range finders and/or GIS maps) and type that information into the form. Please attach additional information including GIS maps, lists of potable well locations, etc.

Receptors

1. Are there Residential Dwellings Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No

   If Yes, how many? 1
   What are the three closest distances from the *Edge of Waste*? ±850 Feet ____ Feet ____ Feet

2. Are there Potable Wells Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No

   If Yes, how many? 1
   What are the three closest distances from the *Edge of Waste*? ±850 Feet ____ Feet ____ Feet

3. Are there Community/Municipal Wells Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No

   If Yes, how many? ____
   What are the three closest distances from the *Edge of Waste*? ____ Feet ____ Feet ____ Feet

4. Are there Surface Water Bodies Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No

   If Yes, how many? 3
   What are the three closest distances from the *Edge of Waste*? ±50 Feet ±50 Feet ±50 Feet

   Please list the names of the water bodies: ____

5. Is Public Water Available Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No

   If Yes, how many of the Residential Dwellings noted above are connected? ____

Corrective Measures

6. Is there an active methane extraction system (blower, flare, etc.)? ☐ Yes ☒ No
7. Is there a passive methane extraction system (trench, vents in cap, flare, etc.)? ☐ Yes ☒ No
8. Is there groundwater remediation taking place on site? ☐ Yes ☒ No

   If Yes, what is the specific remedial technology used? ____

Comments

Please see attachment for location of residential dwelling with potable well within 1500' of the edge of waste. The aerial was taken from Edgecombe County's GIS web site.