



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

**UNIT TYPE:**

Lined MSWLF		LCID		YW		Transfer		Compost		LASA	<b>X</b>	<b>COUNTY:</b> Hyde <b>PERMIT NO.:</b> LASA-48-03 <b>FILE TYPE:</b> COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDLF		Tire Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

**Date of Inspection:** 26 June 2013

**Date of Last Inspection:** 14 November 2012

**FACILITY NAME AND ADDRESS:**

Pungo River Lime Co Storage Facility  
 Smithwick Road  
 Ponzer, NC 27810

**GPS COORDINATES:** **N:** 35.46735 **E:** 076.85943

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Darren Armstrong  
 252.943.2815

**FACILITY CONTACT ADDRESS:**

Pungo River Lime Company, Inc  
 PO Box 134  
 429 W Main Street  
 Belhaven, NC 27810

**Attn: Darren Armstrong**

E-mail: [prlime@gotricounty.com](mailto:prlime@gotricounty.com)

**PARTICIPANTS:**

Ray Williams; NCDENR-Solid Waste

**STATUS OF PERMIT:**

Expired; Approval for Storage of Lime Mud and Wood Ash issued 24 June 2010; expired 24 June 2012. \*For Facility Notification renewal, please contact Elizabeth Patterson; Environmental Technician with the Composting & Land Application Branch at 919.707.8286 or via e-mail at: [Elizabeth.Patterson@ncdenr.gov](mailto:Elizabeth.Patterson@ncdenr.gov)

**PURPOSE OF SITE VISIT:**

Comprehensive Facility Compliance Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

None applicable

**OBSERVED VIOLATIONS:**

None; please see ADDITIONAL COMMENTS section below.

**ADDITIONAL COMMENTS:**

- 1) This Facility is a Lime Mud and Wood Ash storage site.
- 2) The site is secured by a locked gate at the facility entrance.
- 3) The Facility access gate was closed and locked upon my arrival.
- 4) No attendant was on-site during this Facility Compliance Inspection.
- 5) This facility is approved to receive for storage:
  - a. Lime Mud from the Weyerhaeuser Paper Mill in Vanceboro, Craven County, NC.
  - b. Wood ash from Craven Wood Energy in Clarks, Craven County, NC.
- 6) This facility may store lime mud and wood ash for re-use for up to eight months.
- 7) The facility access road is of all-weather construction and appears well maintained at this time.
- 8) The waste types were reviewed. No unpermitted materials were observed on-site during this Facility Compliance Inspection.

**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

LASA4803-20130626INSP

Page 2 of 2



- 9) Sedimentation control fences have been installed around the Facility to prevent the release of lime mud and wood ash from the site during rain events.



- 10) No off-site erosion or surface water run-off was observed during this Facility Compliance Inspection.  
 11) Please ensure that the height of the storage piles does not exceed fifteen feet.  
 12) Please continue to ensure that a 50' buffer is maintained from all property boundaries and surface water ditches.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.

*Ray Williams*

*Ray Williams; Environmental Senior Specialist* Phone: 252.948.3955 E-mail: [ray.williams@ncdenr.gov](mailto:ray.williams@ncdenr.gov)

***Regional Representative***

<b>Delivered on :</b> <u>27 June 2013</u> <b>by</b>	X	Electronic delivery		US Mail	Certified No. [ ]
---	---	---------------------	--	---------	-------------------

cc: James Blount; Director/Hyde County Solid Waste: [jbount@hydecountync.gov](mailto:jbount@hydecountync.gov)  
 Dennis E Shackelford; Eastern District Supervisor/SWS: [dennis.shackelford@ncdenr.gov](mailto:dennis.shackelford@ncdenr.gov)  
 Jessica Montie; Chief Compliance Officer/SWS: [jessica.montie@ncdenr.gov](mailto:jessica.montie@ncdenr.gov)

C: \2013\Hyde\Notifications\LASA-48-03\Audits\LASA4803-20130626INSP  
 NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>

Go Green! Thank you for helping NCDENR be environmentally responsible.

One  
 North Carolina  
*Naturally*