



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID Notification	<b>X</b>	YW		Transfer		Compost		SLAS	<b>COUNTY: Carteret</b> <b>NOTIFICATION NO.: N0047</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

**Date of Site Inspection:** 10 January 2013      **Date of Last Inspection:** 4 October 2012

**FACILITY NAME AND ADDRESS:**

Garner Construction LCID Landfill  
Herring-Smith Road  
Newport, NC 28570

**GPS COORDINATES:** **N:** 34.76763 **E:** 76.84158 **N:** 34.77667 **E:** 76.94352

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Morgan L Garner  
252.223.4019

**FACILITY CONTACT ADDRESS:**

Garner Construction  
5970 US Highway 70  
Newport, NC 28570  
**Attn: Morgan Garner**

**PARTICIPANTS:**

Ray Williams; NCDENR-Solid Waste

**STATUS OF PERMIT:**

Active: Landclearing and Inert Debris (LCID) Landfill Notification

**PURPOSE OF SITE VISIT:**

Comprehensive Facility Inspection

**STATUS OF PAST NOTED VIOLATIONS:**

None applicable

**OBSERVED VIOLATIONS:**

None

**ADDITIONAL COMMENTS:**

- 1) This facility is a Land-clearing and Inert Debris Landfill Notification.
- 2) This facility is recorded with the Carteret County Register of Deeds at: Book # 0193; Page # 0042.
- 3) The access road to the facility is being managed properly at this time.
- 4) No attendant was on-site and the facility was secured by a locked gate during this Facility Compliance Inspection.
- 5) A coppice cover has been established over the entire landfill and no off-site erosion was noted during this Facility Compliance Inspection.
- 6) This facility appears to be inactive; no new activity appears to have taken place since the last Facility Compliance Inspection. \*Please contact your regional Environmental Senior Specialist at the number listed below to begin proper Facility Closure Procedures.
- 7) The waste type being disposed is LCID waste only; no unacceptable waste streams were noted during this Facility Compliance Inspection.
- 8) The perimeter of the landfill has not been staked to identify the landfill footprint. \*Please erect markers delineating the landfill waste footprint boundaries and all required buffers as listed in 15A NCAC 13B .0564 (9) on your LCID notification form.
- 9) There is no sign posted at the facility entrance. \*Please erect a sign at the facility entrance gate showing the facility emergency contact name and number.
- 10) Digital photographs were taken during this Facility Compliance Inspection.


**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

N0047-20130110INSP

Page 2 of 2

11) \*Corrective actions are needed as a result of this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.



Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: [ray.williams@ncdenr.gov](mailto:ray.williams@ncdenr.gov)

***Regional Representative***

Delivered on : <u>14 January 2013</u> by	X	Electronic delivery		US Mail		Certified No. [ ]
--	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: [dennis.shackelford@ncdenr.gov](mailto:dennis.shackelford@ncdenr.gov)  
Jessica Montie; Chief Compliance Officer/SWS: [jessica.montie@ncdenr.gov](mailto:jessica.montie@ncdenr.gov)

C: \\2013\Carteret\Notifications\N0047\Audits\N0047-20130110INSP  
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>