



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:

Lined MSWLF	LCID Notification	X	YW	Transfer	Compost	SLAS	COUNTY: Carteret		
Closed MSWLF	HHW		White goods	Incin	T&P	FIRM	NOTIFICATION NO.: N0218		
CDFL	Tire T&P / Collection		Tire Monofill	Industrial Landfill	DEMO	SDTF	FILE TYPE: COMPLIANCE		

Date of Site Inspection: 10 January 2013 **Date of Last Inspection:** 4 October 2012

FACILITY NAME AND ADDRESS:

Larry Styron LCID Landfill
Herring-Smith Road
Newport, NC 28570

GPS COORDINATES: N: 34.76937 E: 76.84432

FACILITY CONTACT NAME AND PHONE NUMBER:

Tina Sibley
252.422.8404

FACILITY CONTACT ADDRESS:

Styron Properties
PO Box 1599
Morehead City, NC 28570
E-mail: tsibley@ec.rr.com

PARTICIPANTS:

Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Active: Landclearing and Inert Debris (LCID) Landfill Notification

PURPOSE OF SITE VISIT:

Comprehensive Facility Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable

OBSERVED VIOLATIONS:

None

ADDITIONAL COMMENTS:

- 1) This facility is a Land-Clearing and Inert Debris (LCID) Landfill Notification.
- 2) This facility is recorded with the Carteret County Register of Deeds at: Book 913; Page 399.
- 3) This facility is monitored by a 24 hour security camera placed adjacent the facility access road.
- 4) This facility is secured by a locked gate at the facility entrance and has controlled access for safety. The gate was closed and locked during this Facility Compliance Inspection.
- 5) The access road to the facility is being managed properly at this time.
- 6) The facility has been capped and is no longer receiving waste. However, the facility operator wishes to maintain active status for possible future use.
- 7) The facility sign has been damaged. *Please re-post proper signage at the facility entrance stating the facility emergency contact number and types of waste accepted.
- 8) *Please re-install the landfill footprint markers to delineate the waste boundaries.
- 9) Soil has been stockpiled on-site for use in cover maintenance adjacent to the old landfill access ramp.
- 10) A cover crop of native warm season grasses has been established throughout the facility. *Please mow the perimeter of the landfill for more efficient Facility Inspections and maintenance.
- 11) Digital photographs were taken during this Facility Compliance Inspection.
- 12) *Corrective actions are needed as a result of this Facility Compliance Inspection.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0218-20130110INSP

Page 2 of 2

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.



Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on : <u>14 January 2013</u> by	X	Electronic delivery		US Mail		Certified No. []
---	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
Jessica Montie; Chief Compliance Officer/SWS: Jessica.montie@ncdenr.gov

C: \\2013\Carteret\Notifications\N0218\Audits\N0218-20130110INSP
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>