



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:

Lined MSWLF		LCID Notification	X	YW		Transfer		Compost		SLAS		COUNTY: Carteret NOTIFICATION NO.: N0218 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 19 June 2013

Date of Last Inspection: 10 January 2013

FACILITY NAME AND ADDRESS:

Larry Styron LCID Landfill
 Herring-Smith Road
 Newport, NC 28570

GPS COORDINATES: N: 34.76937 E: 76.84432

FACILITY CONTACT NAME AND PHONE NUMBER:

Tina Sibley
 252.422.8404

FACILITY CONTACT ADDRESS:

Styron Properties
 PO Box 1599
 Morehead City, NC 28570
 E-mail: tsibley@ec.rr.com

PARTICIPANTS:

Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Active: Landclearing and Inert Debris (LCID) Landfill Notification for a site less than 2 acres in size.

PURPOSE OF SITE VISIT:

Comprehensive Facility Compliance Inspection

STATUS OF PAST NOTED VIOLATIONS:

None applicable

OBSERVED VIOLATIONS:

No violations were observed during this Facility Compliance Inspection. Please see ADDITIONAL COMMENTS section below.

ADDITIONAL COMMENTS:

- 1) This Facility is a Land-Clearing and Inert Debris (LCID) Landfill Notification.
- 2) This Facility is recorded with the Carteret County Register of Deeds at: Book 913; Page 399.
- 3) This Facility is permitted to receive for disposal:
 - a. Land Clearing Waste: stumps, trees, limbs, brush, grass, and other naturally occurring vegetative materials generated solely from land clearing activities.
 - b. Yard Trash: brush, grass, tree limbs, and similar vegetative materials resulting from landscaping and yard maintenance.
 - c. Inert Debris and Untreated Wood: concrete, brick, concrete block, uncontaminated soil, gravel and rock, untreated and unpainted wood; and
 - d. Used Asphalt: used asphalt or asphalt mixed with dirt, sand, gravel, rock, and concrete.
- 4) The disposal area for this Facility may not exceed 2 acres in total size.
- 5) This Facility is monitored by a 24 hour security camera placed adjacent the facility access road.
- 6) This Facility is secured by a locked gate at the facility entrance and has controlled access for safety. The gate was closed and locked and no attendant was on site during this Facility Compliance Inspection.
- 7) The access road to the Facility is being managed properly at this time.
- 8) The Facility has been capped and is no longer receiving waste. However, the facility operator wishes to maintain active status for possible future use.


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0218-20130619INSP

Page 2 of 2

- 9) The Facility sign has been damaged. *Please re-post proper signage at the facility entrance stating the facility emergency contact number and types of waste accepted.
- 10) The landfill disposal footprint markers have been knocked down and/or removed. *Please re-install the landfill footprint markers to delineate the waste disposal boundaries.
- 11) Soil has been stockpiled on-site for use in cover maintenance in an area adjacent to the landfill access ramp.
- 12) A cover crop of native warm season grasses has been established throughout the facility. *Please mow the perimeter of the landfill for more efficient Facility Inspections and maintenance.
- 13) A cover crop of native warm season grasses has been established throughout the facility; however, the cover crop is sparse in many areas throughout the landfill and is not sufficient to prevent erosion of your landfill cap system. *Please grade, seed, and mulch all areas of sparse cover to establish a groundcover suitable to prevent erosion of your landfill cap system.
- 14) Digital photographs were taken during this Facility Compliance Inspection.
- 15) *Corrective actions are required as a result of this Facility Compliance Inspection Report.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.



Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on : <u>20 June 2013</u> by	X	Electronic delivery		US Mail		Certified No. []
---------------------------------------	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
Jessica Montie; Chief Compliance Officer/SWS: Jessica.montie@ncdenr.gov

C: \\2013\Carteret\Notifications\N0218\Audits\N0218-20130619INSP
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>