



FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

UNIT TYPE:											
Lined MSWLF		LCID Notification	X	YW		Transfer		Compost		SLAS	COUNTY: Carteret NOTIFICATION NO.: N0655 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incin		T&P		FIRM	
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF	

Date of Site Inspection: 21 September 2012 **Date of Last Inspection:** 11 September 2012

FACILITY NAME AND ADDRESS:

Anna Wink LCID Landfill
 Anna Wink Road
 Newport, NC 28570

GPS COORDINATES: N: 34.77667 E: 76.94352

FACILITY CONTACT NAME AND PHONE NUMBER:

Tina Sibley
 252.422.8404

FACILITY CONTACT ADDRESS:

Styron Properties
 PO Box 1599
 Morehead City, NC 28570
 E-mail: tsibley@ec.rr.com

PARTICIPANTS:

Larry Styron; Styron Properties
 Ray Williams; NCDENR-Solid Waste

STATUS OF PERMIT:

Active: Landclearing and Inert Debris (LCID) Landfill Notification

PURPOSE OF SITE VISIT:

Comprehensive Facility Inspection

STATUS OF PAST NOTED VIOLATIONS:

- 1) **15 NCAC 13B .0566 OPERATIONAL REQUIREMENTS FOR LAND CLEARING AND INERT DEBRIS (LCID) LANDFILLS (2) The facility shall only accept those solid wastes which it is permitted to receive. RESOLVED**

OBSERVED VIOLATIONS:

None

ADDITIONAL COMMENTS:

- 1) This facility is a Land-Clearing and Inert Debris Landfill Notification.
- 2) This facility is recorded with the Carteret County Register of Deeds at: Book 913; Page 399.
- 3) The access road to the facility is being managed properly at this time.
- 4) This facility is secured by a locked cable at the facility entrance and has controlled access for safety.
- 5) Proper signage has been posted at the facility entrance.
- 6) No off-site erosion was noted during this Facility Compliance Inspection.
- 7) The landfill working face was less than one acre and is being maintained in a manageable size; however, waste from the working face has been pushed over the southern side slope of the landfill. *As per our conversation, please ensure that the active working face is covered monthly or when it approaches one acre in size, whichever occurs first.
- 8) Overall, the landfill side slopes have been covered adequately and graded to promote positive drainage of surface waters; however, waste from the active working face has been disposed over the southern side slope which needs to be covered and graded. *As per our conversation, please compact, cover and grade the entire southern side slope at a slope not


FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

N0655-20120921RES

Page 2 of 2

- greater than 3:1. This area should then be seeded and mulched to establish a groundcover suitable to prevent erosion of the landfill cap.
- 9) * As per our conversation, please re-install markers delineating your landfill footprint boundaries and all required buffers.
 - 10) Soil has been stockpiled for use as cover in the cleared area adjacent to the western side slope of the landfill.
 - 11) * As per our conversation, please ensure the perimeter road is clear and well maintained, providing for stable access around the facility.
 - 12) Digital photographs were taken during this Facility Compliance Inspection.
 - 13) * Corrective actions are needed as a result of this Facility Compliance Inspection.

Please contact me if you have any questions or concerns regarding this Facility Compliance Inspection Report.



Ray Williams; Environmental Senior Specialist Phone: 252.948.3955 E-mail: ray.williams@ncdenr.gov

Regional Representative

Delivered on : <u>28 September 2012</u> by	X	Electronic delivery		US Mail		Certified No. []
---------------------------------------------------	---	---------------------	--	---------	--	-------------------

cc: Dennis E Shackelford; Eastern District Supervisor/SWS: dennis.shackelford@ncdenr.gov
Jessica Montie; Chief Compliance Officer/SWS: jessica.montie@ncdenr.gov

C: \2012\Carteret\Notifications\N0655\Audits\N0655-20120921RES
NCDENR CARA Portal: <https://edm.nc.gov/DENR-Portal/>