



**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

<b>UNIT TYPE:</b>											
Lined MSWLF		LCID		YW		Transfer		Compost	SLAS	<input checked="" type="checkbox"/>	<b>COUNTY: BURKE</b> <b>PERMIT NO.: SLAS-12-05</b> <b>FILE TYPE: COMPLIANCE</b>
Closed MSWLF		HHW		White goods		Incin		T&P	FIRM		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO	SDTF		

**Date of Site Inspection:** 12/4/2012

**Date of Last Inspection:** 7/18/2012

**FACILITY NAME AND ADDRESS:**

Williams Septic Tank Service  
 Dogwood Vista Road (SR-1514)  
 Chesterfield, NC

**GPS COORDINATES:** N: 35.8047 E: -81.5906

**FACILITY CONTACT NAME AND PHONE NUMBER:**

Marshall R. Williams  
 Telephone: (828) 728-7116

**FACILITY CONTACT ADDRESS:**

P.O. Box 546  
 Hudson, NC 28638

**PARTICIPANTS:**

Troy Harrison – Solid Waste Section  
 Deb Aja – Solid Waste Section

**STATUS OF PERMIT:**

Active. The Permit was issued on August 14, 2008, and shall expire on August 14, 2013.

**PURPOSE OF SITE VISIT:**

Partial Inspection.

**STATUS OF PAST NOTED VIOLATIONS:**

Not applicable.

**OBSERVED VIOLATIONS:**

No violations were observed.

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.


**FACILITY COMPLIANCE INSPECTION REPORT**  
**Division of Waste Management**  
**Solid Waste Section**

Page 2 of 2

**ADDITIONAL COMMENTS**

1. The inspection was conducted to collect annual soil samples and to perform a partial inspection of operations.
2. The facility is permitted for land application of domestic septage (including portable toilet waste) and grease septage.
3. Proper signage was posted at the site entrance.
4. The septage land application site consists of two adjacent fields totaling 6.5 acres.
5. One composite soil sample was collected from each of the two fields. Both fields were in operation.
6. It appeared that all discharges were made within permitted septage boundaries. There were no lateral drifts or debris observed in buffer areas.
7. The applications of septage appeared to have been in accordance with permit conditions. It appeared that loads were discharged and distributed in a manner that there was no standing water or septage.
8. There were no bare areas or areas with dead or stressed vegetation. The fields were mowed.
9. There were no ruts greater than three inches deep observed in the fields.
10. No vectors or odors were noted during the inspection.
11. The access road was well maintained.

Please contact me if you have any questions or concerns regarding this inspection report.

  
 \_\_\_\_\_  
 Deborah Aja  
 Environmental Senior Specialist  
**Regional Representative**  
[deborah.aja@ncdenr.gov](mailto:deborah.aja@ncdenr.gov)

Phone: (828) 296-4702  
 Asheville Regional Office  
 2090 US Hwy 70  
 Swannanoa, NC 28778

<b>Sent on: December 7, 2012</b> to Marshall R. Williams and Darlene Williams by:		Email		Hand delivery	<b>X</b>	US Mail		Certified No.
---	--	-------	--	---------------	----------	---------	--	---------------

Ec: Tony Gallagher, Composting and Land Application Branch Supervisor  
 Jason Watkins, Western District Supervisor  
 Bill Wagner, Environmental Senior Specialist, Solid Waste Section  
 Elizabeth Patterson, Composting and Land Application Branch